

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE E B 11		CAUSE CODE E 12		CAUSE SUBCODE X 13		COMP. SUBCODE D 15		VALVE SUBCODE Z 16	
COMPONENT CODE G E N E R A 14		SEQUENTIAL REPORT NO. 0 1 5		OCCURRENCE CODE / 3		REPORT TYPE L		REVISION NO. /	
ACTION TAKEN X 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22	
ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER P 3 1 8 26			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS <div style="border: 1px solid black; padding: 2px; display: inline-block;">1 5</div> <div style="border: 1px solid black; padding: 2px; display: inline-block;">E</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px; display: inline-block;">28</div>	% POWER <div style="border: 1px solid black; padding: 2px; display: inline-block;">0 9</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px; display: inline-block;">29</div>	OTHER STATUS <div style="border: 1px solid black; border-radius: 50%; padding: 2px; display: inline-block;">30</div> <div style="border: 1px solid black; padding: 2px; display: inline-block;">NA</div>	METHOD OF DISCOVERY <div style="border: 1px solid black; padding: 2px; display: inline-block;">B</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px; display: inline-block;">31</div>	DISCOVERY DESCRIPTION <div style="border: 1px solid black; border-radius: 50%; padding: 2px; display: inline-block;">32</div> <div style="border: 1px solid black; padding: 2px; display: inline-block;">During performance of ST 5081.01</div>
ACTIVITY CONTENT RELEASED OF RELEASE <div style="border: 1px solid black; padding: 2px; display: inline-block;">1 6</div> <div style="border: 1px solid black; padding: 2px; display: inline-block;">Z</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px; display: inline-block;">33</div>			AMOUNT OF ACTIVITY <div style="border: 1px solid black; border-radius: 50%; padding: 2px; display: inline-block;">35</div> <div style="border: 1px solid black; padding: 2px; display: inline-block;">Z</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px; display: inline-block;">34</div>	
<div style="border: 1px solid black; padding: 2px; display: inline-block;">NA</div>			LOCATION OF RELEASE <div style="border: 1px solid black; border-radius: 50%; padding: 2px; display: inline-block;">36</div> <div style="border: 1px solid black; padding: 2px; display: inline-block;">NA</div>	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

7 8 9 10 80  
 PUBLICITY  
 ISSUED DESCRIPTION (45) 8304120455 830331  
 PDR ADOCK 05000346  
 S PDR NRC USE ONLY  
 2 0 N (44) NA 68 69 80

TOLEDO EDISON COMPANY  
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE  
SUPPLEMENTAL INFORMATION FOR LER NP-33-83-16

DATE OF EVENT: March 4, 1983

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Inoperable Emergency Diesel Generator (EDG) due to breaker failure and diesel speed instability

Conditions Prior to Occurrence: The unit was in Mode 1, with Power (MW) = 2737 and Load (Gross MWE) = 907.

Description of Occurrence: At 1120 hours on March 4, 1983, while performing the Diesel Generator (DG) #1 Monthly Surveillance Test ST 5081.01, the generator output became unstable with oscillations in KW, KVARs, AND PF and was declared inoperable. In the process of investigating these oscillations, the generator output breaker failed to operate one time and required a spare breaker to be installed. With the one EDG inoperable, the station was placed in the action statement of Technical Specification 3.8.1.1.

The requirements to demonstrate the remaining AC power sources operable per Surveillance Requirements 4.8.1.1.1.a and 4.8.1.1.2.a.4 were completed at 1149 hours and once every eight hours until DG #1 was again demonstrated operable at 1540 hours on March 5, 1983.

Designation of Apparent Cause of Occurrence: The generator output breaker problem was due to a component failure. The breaker failed to operate because its rack-in mechanism was worn, which allowed the breaker to move enough in its cubicle to open the rack-in interlock in its control circuitry, preventing the breaker from closing again.

The generator oscillation problem could not be determined but was isolated to the electronic governor control system.

Analysis of Occurrence: There was no danger to the health and safety of the public or station personnel. The remaining AC sources remained operable during this time frame.

Corrective Action: Toledo Edison is presently awaiting assistance from Westinghouse to repair the breaker.

The oscillation problem investigation included operating the DG with the electric governor removed from service and the hydraulic governor installed. The hydraulic governor controlled speed and load satisfactorily. The vendor representative was contacted and arrived on site on March 5, 1983. The electronic governor was checked internally to ensure that there were no loose parts. The control switches, electrical connectors, and linkages were also checked, however, no problems were found. The diesel generator was repeatedly tested satisfactorily, and Surveillance Test ST 5081.01 was

TOLEDO EDISON COMPANY  
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE  
SUPPLEMENTAL INFORMATION FOR LER NP-33-83-16  
PAGE 2

successfully performed, and EDG 1-1 was declared operable at 1540 hours on March 5, 1983, removing the unit from the action statement. Surveillance Test ST 5081.01 is presently being performed at twice the required frequency to ensure operability of the emergency diesel generators.

Failure Data: A previous similar occurrence involving the failure of the generator breaker to close was reported in Licensee Event Report NP-33-78-74 (78-062).

Previous similar occurrences involving oscillations in the generator output were reported in Licensee Event Reports NP-33-79-146 (79-126) and NP-33-78-58 (78-049).

LER #83-015