

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	9					14	15											25	26							30	57	CAT	58
LICENSEE CODE		LICENSE NUMBER																LICENSE TYPE												

CON'T

0 1 7 8

REPORT SOURCE

L 6 0 5 0 0 0 3 1 8 7 0 3 0 9 8 3 8 0 3 3 1 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operations, routine log readings revealed metroscope indi-
0 3 | cation for all CEA's was 3 to 5 inches greater than actual position.
0 4 | Under this condition, CEA motion inhibit was inoperable for the power
0 5 | dependent insertion limit function (T.S. 3.1.3.1.b). The condition was
0 6 | corrected four hours after discovery. The redundant position indication
0 7 | system remained operable during this event.
0 8 | Similar events: none.

0 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE		
7	8	R	B	X	Z	I	N	S	T	R	U	Y	Z				
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
LER/RO REPORT NUMBER		8	3	0 1 9		0 3		L		0							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
E	Z	Z		Z		Z		0 0 0 0		N		N		N		M 2 8 5	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause for this event was the zero shift of the front scanner module;
1 1 | probable cause: circuit burn in of newly installed circuit boards. The
1 2 | module's front scanner board was adjusted for proper reed switch/metro-
1 3 | scope position correlation; indication was monitored for 2 weeks with no
1 4 | shift noted. No further corrective or preventive actions necessary.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) 1 5 E

% POWER 1 0 0 (29) N/A

OTHER STATUS (30)

METHOD OF DISCOVERY (31) A

DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE

1	6	2	33	2	34	N/A	
7	8	9	10	11			44

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A	
45	

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) N/A	(39)		

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
			N/A

7		8		9		11		12	
LOSS OF OR DAMAGE TO FACILITY									
TYPE		DESCRIPTION							
1	9	Z	42	N/A					

8204130501 000000

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 N (44) N/A
B304120501 830331
PDR ADOCK 05000318
S PDR
NRC USE ONLY

NAME OF PREPARER P. A. Pieringer/J.W. Raynor

PHONE: 301-269-4742/4713