

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S	C	V	C	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	0	0	0	4	5										
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34										
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE										CAT		58	

CONT

0	1	L	6	0	5	0	0	0	3	9	5	7	0	3	1	1	8	3	8	0	4	0	8	8	3	9					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33					
REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0620 hours on March 11, 1983, with the Plant operating in Mode 1, Main

0 3 | Steamline "C" Radiation Monitor experienced spurious alarms. The monitor was

0 4 | declared inoperable. The applicable Technical Specification Action Statement was

0 5 | entered. A maintenance work request was issued to investigate the problem. The

0 6 | potential for any adverse consequences was minimized as the Plant has not

0 7 | experienced any primary-to-secondary system leakages.

0 8 |

0	9	B	A	11	E	12	C	13	I	N	S	T	R	U	14	E	15	Z	16												
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26												
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE															
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32	
X		F		Z		Z		0		0		0		0		Y		N		A		V		1		1		5			
33		34		35		36		37		38		39		40		41		42		43		44		45		46		47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The monitor was returned to operability at 0700 hours on March 12, 1983, after the

1 1 | satisfactory completion of an operational test and calibration check. Upon re-

1 2 | installation of the detector, small signal oscillations were still observed. The

1 3 | event is attributed to a slack detector cable, which allowed signal oscillations

1 4 | induced by vibrations. The detector cable will be more adequately secured.

1	5	B	28	0	5	0	29	N/A	30	A	31	Operator Observation	32						
7	8	9	10	11	12	13	14	15	16	17	18	19	20						
FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
ACTIVITY CONTENT				AMOUNT OF ACTIVITY				LOCATION OF RELEASE											
16				17				18				19				20			
Z				Z				N/A				N/A				N/A			
33				34				35				36				37			

1	7	0	0	0	37	Z	38	N/A	39		
7	8	9	10	11	12	13	14	15	16		
PERSONNEL EXPOSURES				DESCRIPTION							
NUMBER				TYPE				DESCRIPTION			

1	8	0	0	0	40	N/A	41				
7	8	9	10	11	12	13	14				
PERSONNEL INJURIES				DESCRIPTION							
NUMBER				TYPE				DESCRIPTION			

1	9	Z	42	N/A	43
7	8	9	10	11	12
LOSS OF OR DAMAGE TO FACILITY				DESCRIPTION	
TYPE				DESCRIPTION	

2	0	N	44	N/A	45
7	8	9	10	11	12
PUBLICITY ISSUED				DESCRIPTION	
NUMBER				DESCRIPTION	

NAME OF PREPARER

H. C. Fields
H. C. Fields

PHONE: (803) 345-5209

NRC USE ONLY