

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	I	C	C	2	0	0	-	10	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4	5	
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE						30	CAT		58

CON'T

REPORT  
SOURCE

0 1 8  
REPORT SOURCE L 6 0 5 0 0 0 3 1 5 7 0 3 1 0 8 3 8 0 4 0 8 8 3 9  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | DURING NORMAL OPERATION, THE A-B DIESEL GENERATOR (D.G.) INVERTER FAILED TWICE

03, RENDERING THE A-B D.G. INOPERABLE. THIS IS NON-CONSERVATIVE IN RESPECT TO TECHNICAL

04, SPECIFICATION 3.8.1.1.b. THE APPROPRIATE ACTION REQUIREMENT WAS FULFILLED AS THE

05 C-D D.G. WAS STARTED AND THE CORRECT BREAKER ALIGNMENTS WERE VERIFIED.

06 \_\_\_\_\_

U	R	
---	---	--

0 9  
 9 10  
 SYSTEM CODE  
 E E 11  
 CAUSE CODE  
 X 12  
 CAUSE SUBCODE  
 Z 13  
 COMPONENT CODE  
 G E N E R A 14  
 COMP. SUBCODE  
 F 15  
 VALVE SUBCODE  
 Z 16

(17) LER RO REPORT NUMBER 83 — 023 / 03 L — 0

ACTION TAKEN 33 ☒ 13 FUTURE ACTION 34 ☒ 19 EFFECT ON PLANT 35 ☒ 20 SHUTDOWN METHOD 36 ☒ 21 HOURS 37 0 0 0 0 40 ATTACHMENT SUBMITTED 41 ☒ Y 23 NPDR-4 FORM SUB. 42 ☒ Y 24 PRIME COMP. SUPPLIER 43 ☒ A 25 COMPONENT MANUFACTURER 44 S 2 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 INVESTIGATION REVEALED THAT THE INVERTER (MANUF. BY SOLIDSTATE CONTROLS INC.) FAILURE

WERE DUE TO BLOWN FUSES. THESE FAILURES WERE MOST PROBABLY CAUSED BY HIGH AMBIENT

ROOM TEMPERATURE. THE D.G. ROOM INLET VENTILATION DAMPERS WERE FOUND WIRED SHUT.

THESE DAMPERS WERE OPENED AND THE ROOM TEMPERATURE WAS LOWERED. SEE THE ATTACHED

1 3 SUPPLEMENT FOR ADDITIONAL INFORMATION.

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION								
1	5	E	(28)	1	0	0	(29)	NA	(30)	A	(31)	AUDIBLE ALARMS	(32)

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES		DESCRIPTION	
NUMBER	TYPE		
8	6	7	33
9	7	10	34
		11	NA
		44	
		45	NA

NUMBER			TYPE		DESCRIPTION	
1	7	000	(37)	Z	(38)	NA
8	9	11	12	13		
PERSONNEL INJURIES						

NUMBER		DESCRIPTION
1	000	NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	

8 9 10  
PUBLICATION  
ISSUED DESCRIPTION (45)  
8304150397 830408  
PDR ADOCK 05000315  
NRC USE ONLY

NAME OF PREPARER J. L. RISCHLING

8304150397 830408  
PDR ADDCK 05000315  
S PDR

NAC USE ONLY

PHONE: 616-465-5901

ATTACHMENT TO LER# 83-023/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

INVESTIGATION REVEALED THAT THE INITIAL LOSS OF THE INVERTER WAS DUE TO A BLOWN FUSE (FUSE NO. FU2). THE INVERTER WAS INSPECTED FOR DAMAGED COMPONENTS AND THE FUSE WAS REPLACED. THE INVERTER WAS TESTED AND THE AFFECTED D.G. WAS RUN FOR AN OPERABILITY CHECK. SEVERAL HOURS LATER THE INVERTER FAILED AGAIN AS THE SAME FUSE BLEW WITH NO OTHER COMPONENT FAILURES. FURTHER INVESTIGATION REVEALED THAT THE A-B D.G. ROOM TEMPERATURE WAS 108 DEGREES F. THIS WAS IN EXCESS OF THE INVERTER MANUFACTURERS OPERATING SPECIFICATION. IT WAS FOUND THAT THE VENTILATION INLET DAMPERS WERE WIRED SHUT AND ELECTRICALLY DISCONNECTED. THE DAMPERS WERE OPENED AND THE D.G. ROOM COOLED DOWN. THE A-B D.G. WAS OPERABILITY TESTED AND DECLARED OPERABLE 9 HOURS FOLLOWING THE INITIAL FAILURE. NO INVERTER FAILURES HAVE OCCURRED SINCE.

THE NEED FOR THE CLOSED VENTILATION INLET DAMPERS IS STILL BEING INVESTIGATED. THIS LER WILL BE UPDATED AS A RESULT OF THIS INVESTIGATION.