

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0 1
7 8

REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 0 3 1 4 8 3 8 0 4 0 6 8 3 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Pressurizer Code Safety Valves 2PR3, 2PR4, and 2PR5 were tested for lift set pressure

03 and seat leakage by Wyle Laboratories during the period of February 24-25, 1983. All

04 valves lifted below the 2485 psig ± 1% pressure range specified in Technical Speci-

05 fication 3.4.3. All valves displayed heavy audible and visual seat leakage at 2236

06 psig. The actual lift pressures were: 2PR3 - 2416 psig (44 psig below), 2PR4 - 2400

07 psig (60 psig below), 2PR5 - 2454 psig (6 psig below).

08		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
08		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
08		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
08		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
08		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73															

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 All three valves have been repaired and retested satisfactorily. They are scheduled
1 1 to be reinstalled. In order to assess the actual impact of the safety valve test
1 2 failures on plant performance during the analyzed transient, an engineering evaluation
1 3 of the occurrence has been requested. A Supplemental Report will be submitted upon
1 4 completion of the evaluation.

8 9
FACILITY STATUS (1) 5 (H) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (C) (31) Pressure Lift Test DISCOVERY DESCRIPTION (32)
7 8 9 10 11 12 13 44 45 46 80

ACTIVITY CONTENT RELEASED OF RELEASE (1) 6 (Z) (33) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)
7 8 9 10 11 12 13 44 45 46 80

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		(37)	Z	(38) NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	40	NA

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) NA
S PDR
PDR ADOCK 05000311
B304180513 B30406

PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N (44) NA
 NRC USE ONLY

NAME OF PREPARER F. Dickey

PHONE: (609) 935-6000 Ext. 3229