

EXHIBIT A

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

<u>7</u>	<u>0</u>	<u>1</u>	<u>8</u>	<u>9</u>	A	R	I	A	N	O	<u>2</u>	<u>12</u>	<u>15</u>	<u>0</u>	<u>0</u>	-	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	-	<u>1</u>	<u>0</u>	<u>0</u>	<u>13</u>	<u>26</u>	4	1	1	1	1	1	<u>4</u>	<u>57</u>	CAT	<u>58</u>	
				LICENSEE CODE									LICENSE NUMBER																LICENSE TYPE										
<u>7</u>	<u>0</u>	<u>1</u>	<u>8</u>	REPORT SOURCE	<u>16</u>	<u>61</u>	<u>0</u>	<u>5</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>3</u>	<u>6</u>	<u>8</u>	<u>17</u>	<u>69</u>	<u>0</u>	<u>3</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>8</u>	<u>3</u>	<u>18</u>	<u>75</u>	<u>0</u>	<u>4</u>	<u>0</u>	<u>7</u>	<u>8</u>	<u>3</u>	<u>19</u>							
						DOCKET NUMBER										EVENT DATE								REPORT DATE															

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

[0] [2] | On 3/11/83, while in Mode 1 at 100% full power, containment spray pump 2P-35A tripped because the 'C' phase

[0] [3] | instantaneous overcurrent relay tripped. Containment spray pump 2P-35B and its associated train were operable.

[0] [4] | The pump was being started as part of a surveillance test. Repairs were made and the pump was successfully

[0] [5] | started approximately 3 hours after the pump tripped. This is well within the 72 hours required by the action

[0] [6] | statement of T.S. 3.6.2. This occurrence is reportable per T.S. 6.9.1.9.b. There have been no similar

[0] [7] | occurrences.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP SUBCODE		VALVE SUBCODE		REVISION NO					
10 9 8		5 4 3 2 1		11 10 9 8 7 6 5 4 3 2 1		13 12 11 10 9 8 7 6 5 4 3 2 1		15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1					
17	LER/RO REPORT NUMBER	EVENT YEAR 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		11 10 9 8 7 6 5 4 3 2 1		SEQUENTIAL REPORT NO. 13 12 11 10 9 8 7 6 5 4 3 2 1		OCCURRENCE CODE 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		REPORT TYPE 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		REVISION NO 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1					
ACTION TAKEN 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		FUTURE ACTION 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		EFFECT ON PLANT 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		SHUTDOWN METHOD 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		HOURS 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		ATTACHMENT SUBMITTED 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		NPRD-4 FORM SUB 32 31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		PRIME COMP. SUPPLIER 34 33 32 31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1		COMPONENT MANUFACTURER 36 35 34 33 32 31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | The cause of the event was determined to be deviation from setpoint. The setpoint was determined to be 28 amps
1 1 | versus the normal setpoint of 48 amps. It appears the setpoint was erroneously set during a previous calibra-
1 2 | tion, however, setpoint drift could not be conclusively ruled out as the cause of the event. The relay was
1 3 | reset to 48 amps and reinstalled. The relay will be checked periodically to determine if further setpoint drift
1 4 | occurs. Previous data sheets for these relays were reviewed and no setpoint drift was found during previous

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	1	128	1	0	0	129	1	NA
7	8	9	10	11	12	13	14	15	16
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	1	133	1	134	1	NA	1	NA
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	1	0	0	137	1	138	1	NA
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	1	0	0	140	1	NA	1	NA
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	1	1	142	1	NA	1	NA	1
7	8	9	10	11	12	13	14	15	16

PUBLICITY

ISSUED	DESCRIPTION
--------	-------------

ISSUED		DESCRIPTION		NRC USE ONLY																				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25

NAME OF PREPARER Patrick C. Rogers

PHONE: (501) 964-3100

8304190367 830407
PDR ADOCK 05000368
S PDR

LER No. 83-016/03L-0

Cause Description and Corrective Actions (Continued)
calibrations.