

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 T N S N P 1 200-000000-000 341111 41 5  
7 8 9 14 15 25 26 57 CAT 56  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CONT  
01 REPORT SOURCE L60510003277 033183 8 9  
2 8 60 61 68 69 74 75 80  
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 With unit 1 in mode 1 (100% Rx power) at 1200 CST on 03/31/83, all four 125 volt

03 DC vital battery channels were declared inoperable due to failure to perform the

04 weekly inspection surveillance within its required frequency. The unit complied

05 with LCO 3.0.3. There was no effect upon public health and safety. Previous

06 occurrences - none.

07

08

<span style="border: 1px solid black; padding: 2px;">09</span>	SYSTEM CODE <span style="border: 1px solid black; padding: 2px;">E C</span> <span style="border: 1px solid black; padding: 2px;">11</span>	CAUSE CODE <span style="border: 1px solid black; padding: 2px;">A</span> <span style="border: 1px solid black; padding: 2px;">12</span>	CAUSE SUBCODE <span style="border: 1px solid black; padding: 2px;">C</span> <span style="border: 1px solid black; padding: 2px;">13</span>	COMPONENT CODE <span style="border: 1px solid black; padding: 2px;">Z Z Z Z Z Z</span> <span style="border: 1px solid black; padding: 2px;">14</span>	COMP. SUBCODE <span style="border: 1px solid black; padding: 2px;">Z</span> <span style="border: 1px solid black; padding: 2px;">15</span>	VALVE SUBCODE <span style="border: 1px solid black; padding: 2px;">Z</span> <span style="border: 1px solid black; padding: 2px;">16</span>
	EVENT YEAR <span style="border: 1px solid black; padding: 2px;">83</span> <span style="border: 1px solid black; padding: 2px;">21</span>	SEQUENTIAL REPORT NO. <span style="border: 1px solid black; padding: 2px;">043</span> <span style="border: 1px solid black; padding: 2px;">23</span>	OCCURRENCE CODE <span style="border: 1px solid black; padding: 2px;">01</span> <span style="border: 1px solid black; padding: 2px;">24</span>	REPORT TYPE <span style="border: 1px solid black; padding: 2px;">T</span> <span style="border: 1px solid black; padding: 2px;">27</span>	REVISION NO. <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">28</span>	
	ACTION TAKEN <span style="border: 1px solid black; padding: 2px;">X</span> <span style="border: 1px solid black; padding: 2px;">33</span>	FUTURE ACTION <span style="border: 1px solid black; padding: 2px;">X</span> <span style="border: 1px solid black; padding: 2px;">34</span>	EFFECT ON PLANT <span style="border: 1px solid black; padding: 2px;">Z</span> <span style="border: 1px solid black; padding: 2px;">35</span>	SHUTDOWN METHOD <span style="border: 1px solid black; padding: 2px;">Z</span> <span style="border: 1px solid black; padding: 2px;">36</span>	HOURS <span style="border: 1px solid black; padding: 2px;">0000</span> <span style="border: 1px solid black; padding: 2px;">37</span>	ATTACHMENT SUBMITTED <span style="border: 1px solid black; padding: 2px;">Y</span> <span style="border: 1px solid black; padding: 2px;">40</span>
	NPED-4 FORM SUB. <span style="border: 1px solid black; padding: 2px;">N</span> <span style="border: 1px solid black; padding: 2px;">42</span>	PRIME COMP. SUPPLIER <span style="border: 1px solid black; padding: 2px;">Z</span> <span style="border: 1px solid black; padding: 2px;">43</span>	COMPONENT MANUFACTURER <span style="border: 1px solid black; padding: 2px;">Z 9 9 9</span> <span style="border: 1px solid black; padding: 2px;">44</span>			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Investigation revealed that the late performance of SI-100.1 for weekly inspection

11 of all 125-V D.C. vital battery channels was caused by personnel error in that the

12 maintenance foreman responsible for the work had placed the surveillance instruction

13 (SI) package in his desk and forgot to take it out when it was due. Upon discovery,

14 the performance of the test was completed successfully.

FACILITY STATUS <span style="border: 1px solid black; padding: 2px;">15</span> <span style="border: 1px solid black; padding: 2px;">E</span> <span style="border: 1px solid black; padding: 2px;">28</span>	% POWER <span style="border: 1px solid black; padding: 2px;">100</span> <span style="border: 1px solid black; padding: 2px;">29</span>	OTHER STATUS NA <span style="border: 1px solid black; padding: 2px;">30</span>	METHOD OF DISCOVERY <span style="border: 1px solid black; padding: 2px;">B</span> <span style="border: 1px solid black; padding: 2px;">31</span>	DISCOVERY DESCRIPTION Review of surveillance test <span style="border: 1px solid black; padding: 2px;">32</span>
--	---	---	---	---

ACTIVITY RELEASED <span style="border: 1px solid black; padding: 2px;">16</span> <span style="border: 1px solid black; padding: 2px;">Z</span> <span style="border: 1px solid black; padding: 2px;">33</span>	CONTENT <span style="border: 1px solid black; padding: 2px;">Z</span> <span style="border: 1px solid black; padding: 2px;">34</span>	AMOUNT OF ACTIVITY NA <span style="border: 1px solid black; padding: 2px;">35</span>	LOCATION OF RELEASE NA <span style="border: 1px solid black; padding: 2px;">36</span>
--	---	---	--

PERSONNEL EXPOSURES NUMBER <span style="border: 1px solid black; padding: 2px;">17</span> <span style="border: 1px solid black; padding: 2px;">000</span>	TYPE <span style="border: 1px solid black; padding: 2px;">Z</span> <span style="border: 1px solid black; padding: 2px;">37</span>	DESCRIPTION NA <span style="border: 1px solid black; padding: 2px;">38</span>
---	--	--

PERSONNEL INJURIES NUMBER <span style="border: 1px solid black; padding: 2px;">18</span> <span style="border: 1px solid black; padding: 2px;">000</span>	DESCRIPTION NA <span style="border: 1px solid black; padding: 2px;">40</span>
--	--

LOSS OF OR DAMAGE TO FACILITY TYPE <span style="border: 1px solid black; padding: 2px;">19</span> <span style="border: 1px solid black; padding: 2px;">Z</span> <span style="border: 1px solid black; padding: 2px;">47</span>	DESCRIPTION NA <span style="border: 1px solid black; padding: 2px;">43</span>
--	--

PUBLICITY ISSUED <span style="border: 1px solid black; padding: 2px;">20</span> <span style="border: 1px solid black; padding: 2px;">N</span> <span style="border: 1px solid black; padding: 2px;">44</span>	DESCRIPTION NA <span style="border: 1px solid black; padding: 2px;">45</span>
--	--

8304190537 830413  
PDR ADOCK 05000327  
S PDR

NRC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding

Phone: (615) 870-6422

Sequoyah Nuclear Plant

LER SUPPLEMENTAL INFORMATION

SQRO-50-327/83043

Technical Specification Involved: 3.8.2.3

Reported Under Technical Specification: 6.9.1.12.b

Date of Occurrence: 03/31/83 Time of Occurrence: 1200 CST

Identification and Description of Occurrence:

During a review of surveillance instruction (SI) 100.1 on the weekly inspection of the 125-volt D.C. vital battery channels, it was discovered that the surveillance had not been performed within the LCO required time frequency. This rendered the vital batteries inoperable and the unit complied with LCO 3.0.3.

Conditions Prior to Occurrence:

Unit 1 in mode 1 at 100% Rx power; unit 2 in mode 1 at 75% Rx power.

Apparent Cause of Occurrence:

Investigation revealed that the late performance of the SI package was caused by personnel error in that the maintenance foreman responsible for this work had placed the SI package in his desk and forgot to take it out when it was due to be completed.

Analysis of Occurrence:

The test was required to be completed on 03/30/83. The maintenance foreman was given the surveillance package on 03/28/83 for working. The foreman was short of personnel on that day and placed the package in his desk for working the next day. Inadvertently, the foreman forgot about the package until 03/31/83.

Corrective Action:

Immediately upon discovery, the performance of the surveillance was initiated and successfully completed. The vital batteries were declared operable at 1330 CST on 03/31/83.

Maintenance personnel have been informed of the severity of this incident and instructed to ensure that SI packages are completed on time. Additionally, disciplinary action will be taken against the personnel involved.

Failure Data:

None.