

CONTROL BLOCK:

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	--	---

7 8 9 14 15 25 26 30 57 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	7	2	7	1	2	2	8	8	1	8	0	3	3	0	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On December 28, 1981, an operator discovered a service water leak in the spool piece

0 3 between service water valves 12SW57 and 12SW58, located in the 78' Elevation North

0 4 Penetration Area. The leak was isolated by closing service water valves 12SW54 and

0 5 12SW76, isolating No. 12 Containment Fan Coil Unit (CFCU), rendering it inoperable.

0 6 At 0550 hours Action Statement 3.6.2.3.a was entered.

0 7

0 8

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
7	8	S	B	E	C	P	I	P	E	X	X	C	Z				
		9	10	11	12	13	18				19	20					
(17) LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
81		81		121		03		X		1							
21		22		24		28		30		32							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
F		Z		Z		Z		0000		Y		Y		N		Z999	
33		34		35		36		37		41		42		43		44	
(18)		(19)		(20)		(21)		(22)		(23)		(24)		(25)		(26)	
33		34		35		36		37		41		42		43		44	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | At 0347 hours, January 2, 1982, the plant went into Mode 4. Because Action Statement

1 1 | 3.6.2.3.a is not applicable in Mode 4, it was terminated. Design Change Package (DCP)

1 2 | IEC-0504 was implemented. This DCP replaced the spoolpiece with one made of stainless

1 3 | steel for improved erosion and corrosion resistance.

1	4																	80																																																							
7	8	9																																																																							
FACILITY STATUS			% POWER			OTHER STATUS			(30)	METHOD OF DISCOVERY			DISCOVERY DESCRIPTION						(32)																																																						
1	5	E	(28)	0	6	4	(29)	N/A			(31)	Service Water Leak																																																													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z (33) Z (34) N/A

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A

45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION (39)				
1	7	0	0	0	(37)	Z	(38)	N/A	

PERSONNEL INJURIES		80
NUMBER	DESCRIPTION	
41		

7	8	9	11	12	N/A		80
LOSS OF OR DAMAGE TO FACILITY (43)					8304220199 830330 PDR ADONCK 05000272		
TYPE DESCRIPTION							

1	9	Z	42	N/A	S	PDR
---	---	---	----	-----	---	-----

								PUBLCITY													NRC USE ONLY					
ISSUED		DESCRIPTION		(45)																						
2	0	N	(44)		N/A																					
7	8	9	10												68	69	80									

NAME OF PREPARER R. Heller

PHONE: (609) 935-6000 Ext. 3078