

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)








(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	7
---	---

0	8		8
---	---	--	---

(17) LER/RO REPORT NUMBER

EVENT YEAR			SEQUENTIAL REPORT NO.			OCCURRENCE CODE		REPORT TYPE		NO.	
8	3	—	0	3	3	0	3	L	—	0	
21	22	23	24	25	26	27	28	29	30	31	32

ACTION TAKEN 33 X 18 34 F 19 35 Z 20 36 Z 21 37 0 38 0 39 0 40 22 41 N 23 42 N 24 43 A 25 44 Z 45 9 46 9 47 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The pilot flameout was due to low pressure in the single hydrogen bottle supplying

1 1 both monitors. The bottle was replaced and the monitors were restored to operable

1 2 status within two hours. Low bottle pressure had previously been identified

1 3 but the bottle was not replaced in time to prevent flameout. Administrative

1 4 changes are being pursued to provide more timely hydrogen bottle changes. Further,

7 8 9 a design change to install a back-up hydrogen bottle is in progress.

FACILITY STATUS (1) 5 (2) B (28) % POWER (3) 0 (4) 0 (5) 0 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B (32) DISCOVERY DESCRIPTION (32) Surveillance Test

ACTIVITY CONTENT
RELEASED OF RELEASE

1 5 Z 33 10 Z 34 NA 44

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

45 80

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION					
1	7	0	0	0	(37)	Z	(32)	NA	

[illegible]

1 8 0 0 0 40 NA 8304230070 80

19		Z		42		43	
TYPE		DESCRIPTION					
				NA		8304220372 830414 PDR ADDCK 05000361 S PDR	

7 8 9 10
PUBLICITY
ISSUED M L DESCRIPTION (45)
100 NA
NRC USE ONLY

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

H. B. RAY 714/492-7700

NAME OF PREPARER

PHONE

714/492-7700

NRC USE ONLY

[illegible]