

LICENSEE EVENT REPORT

UPDATE REPORT

PREVIOUS REPORT DATE: 01-15-82

CONTROL BLOCK:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0	1	L	6	0	5	0	0	0	3	1	7	7	1	2	1	6	8	1	8	0	4	1	1	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 0025, during normal operation, Channel B Axial Power trip unit was bypassed for investigation of a failed Axial Shape Index (ASI) Lower Setpoint. Again, on 12-22-81, at 1625, Channel B ASI Lower Setpoint failed. Channel B High Power and Therman Margin/Low Pressure trip units were bypassed during troubleshooting. All trips were returned to service at 1025 on 12-16-81 and at 1030 on 12-23-81. Redundant channels remained operable. Similar events: none.

0	9	I	A	11	X	12	X	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16	17	8	1	0	8	5	0	3	X	1
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	----	---	---	---	---	---	---	---	---	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Troubleshooting revealed an intermittent output failure of Module G4-5 (ASI Drawer). The module was replaced on 12-16-81. The failure occurred again on 12-23-81. Additional troubleshooting revealed no cause of failure. This failure has not recurred in the last 8 months and can be detected by daily log readings. No further action is deemed necessary.

1	5	E	28	1	0	0	29	N/A	A	31	Operator Observation
---	---	---	----	---	---	---	----	-----	---	----	----------------------

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER J. S. Lagiewski/L. S. Hinkle

PHONE 301-269-4747/4986

8304220545 830411
PDR ADDOCK 05000317
S PDR

NRC USE ONLY