

0
0
0
0
0
0
0

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
0 1 N J S G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50									
CON'T																			
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 7 2 7 0 8 3 1 8 2 6 0 3 3 0 8 3 9										7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50									
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10																			
0 2 At 0930 hours, August 31, 1982, a service water leak was discovered on No. 12																			
0 3 Charging Pump lube oil cooler outlet piping. No. 12 Charging Pump was declared																			
0 4 inoperable, therefore, Action Statements 3.5.2a and 3.1.2.4 were entered at																			
0 5 0930 hours.																			
0 6																			
0 7																			
0 8																			
0 9																			
SYSTEM CODE W B 11										CAUSE CODE B 12									
CAUSE SUBCODE B 13										COMPONENT CODE P I P E X X 14									
COMP. SUBCODE A 15										VALVE SUBCODE Z 16									
LER RO REPORT NUMBER 17										EVENT YEAR 8 2 21									
SEQUENTIAL REPORT NO. 0 6 9 24										OCCURRENCE CODE 0 3 28									
REPORT TYPE X 30										REVISION NO. 1 32									
ACTION TAKEN C 18										FUTURE ACTION Z 19									
EFFECT ON PLANT Z 20										SHUTDOWN METHOD Z 21									
HOURS 0 0 0 0 37										ATTACHMENT SUBMITTED Y 23									
NPRD-4 FORM SUB. N 24										PRIME COMP. SUPPLIER A 25									
COMPONENT MANUFACTURER X 9 9 9 44																			
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																			
1 0 The cause was erosion of the piping by silt laden service water. The pipe was																			
1 1 replaced and the pump was tested satisfactorily. No. 12 Charging Pump was																			
1 2 declared operable and Action Statements 3.5.2a and 3.1.2.4 were terminated at 1722																			
1 3 hours. A Design Change Package has been implemented which replaced the piping with																			
1 4 piping made of type 316 stainless steel for greater erosion resistance.																			
FACILITY STATUS E 28										% POWER 1 0 0 29									
OTHER STATUS N/A 30										METHOD OF DISCOVERY A 31									
DISCOVERY DESCRIPTION Operational Event 32																			
ACTIVITY CONTENT RELEASED OF RELEASE Z 33										AMOUNT OF ACTIVITY N/A 35									
LOCATION OF RELEASE N/A 36																			
PERSONNEL EXPOSURES NUMBER 0 0 0 37										TYPE 7 38									
DESCRIPTION N/A 39																			
PERSONNEL INJURIES NUMBER 0 0 0 40										DESCRIPTION N/A 41									
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42										DESCRIPTION N/A 43									
PUBLICITY ISSUED N 44										DESCRIPTION N/A 45									
8304220580 830330 PDR ADOCK 05000272 PDR										NRC USE ONLY									
NAME OF PREPARER R. Heller										PHONE: (609) 935-6000 Ext. 3078									