

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | |1
 1 6

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES TO
On 3/8/83, while in refueling shutdown, Reactor Building (RB) pressure switch PS-2403 was found to be out of tolerance while performing the Reactor Protection System (RPS) channel "D" calibration. Also, on 3/21/83, RB pressure switch PS-2401 was found to be out of tolerance while performing the RPS channel "B" calibration. PS-2401 and PS-2403 were found to open at 18.9 psia, above the maximum Technical Specification Value of 18.7 psia. Since the switches would have actuated at a pressure higher than required, this occurrence is reportable per Technical Specification (TS) 6.12.3.2.a. RB pressure switch PS-2400 for RPS channel "A" and RB pressure switch PS-2402 for RPS channel "C" were found to be set at less than or equal to the value specified in T.S.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE		REVISION NO			
1	0	1	I	1	E	1	I	1	N	1	S	1	S	1	Z	1	1
2	9	2	A	2		2		2	T	2	R	2	U	2		2	
3		3		3		3		3		3		3		3		3	
4		4		4		4		4		4		4		4		4	
5		5		5		5		5		5		5		5		5	
6		6		6		6		6		6		6		6		6	
7		7		7		7		7		7		7		7		7	
8		8		8		8		8		8		8		8		8	
9		9		9		9		9		9		9		9		9	
10		10		10		10		10		10		10		10		10	
11		11		11		11		11		11		11		11		11	
12		12		12		12		12		12		12		12		12	
13		13		13		13		13		13		13		13		13	
14		14		14		14		14		14		14		14		14	
15		15		15		15		15		15		15		15		15	
16		16		16		16		16		16		16		16		16	
17		17		17		17		17		17		17		17		17	
18		18		18		18		18		18		18		18		18	
19		19		19		19		19		19		19		19		19	
20		20		20		20		20		20		20		20		20	
21		21		21		21		21		21		21		21		21	
22		22		22		22		22		22		22		22		22	
23		23		23		23		23		23		23		23		23	
24		24		24		24		24		24		24		24		24	
25		25		25		25		25		25		25		25		25	
26		26		26		26		26		26		26		26		26	
27		27		27		27		27		27		27		27		27	
28		28		28		28		28		28		28		28		28	
29		29		29		29		29		29		29		29		29	
30		30		30		30		30		30		30		30		30	
31		31		31		31		31		31		31		31		31	
32		32		32		32		32		32		32		32		32	

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
1 E 118	1 Z 119	1 Z 120	1 Z 121	1 0 1 0 1 0 1 22	1 Y 123	1 N 124	1 A 125	1 B 1 0 1 8 1 0 1 26
33	34	35	36	37 40	41	42	43	44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | The pressure switches were reset to 18.5 psia per the RPS calibration procedure and returned to service. These

1 1 | pressure switches are snap action type manufactured by Barton.

1	2	
1	3	
1	4	

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	
1 5	H 28	0 0 0 29	N/A	B 31	Routine Surveillance	
7 8	9	10 12	13	44	46	32

ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	2	133	NA	35	NA	36
7	8	9	10	11	44	45	46

PERSONNEL EXPOSURES		DESCRIPTION	
NUMBER	TYPE		
10	137	1	NA
11	138	2	
12		3	
13		4	
14		5	
15		6	
16		7	
17		8	
18		9	
19		10	
20		11	
21		12	
22		13	
23		14	
24		15	
25		16	
26		17	
27		18	
28		19	
29		20	
30		21	
31		22	
32		23	
33		24	
34		25	
35		26	
36		27	
37		28	
38		29	
39		30	
40		31	
41		32	
42		33	
43		34	
44		35	
45		36	
46		37	
47		38	
48		39	
49		40	
50		41	
51		42	
52		43	
53		44	
54		45	
55		46	
56		47	
57		48	
58		49	
59		50	
60		51	
61		52	
62		53	
63		54	
64		55	
65		56	
66		57	
67		58	
68		59	
69		60	
70		61	
71		62	
72		63	
73		64	
74		65	
75		66	
76		67	
77		68	
78		69	
79		70	
80		71	
81		72	
82		73	
83		74	
84		75	
85		76	
86		77	
87		78	
88		79	
89		80	
90		81	
91		82	
92		83	
93		84	
94		85	
95		86	
96		87	
97		88	
98		89	
99		90	
100		91	
101		92	
102		93	
103		94	
104		95	
105		96	
106		97	
107		98	
108		99	
109		100	
110		101	
111		102	
112		103	
113		104	
114		105	
115		106	
116		107	
117		108	
118		109	
119		110	
120		111	
121		112	
122		113	
123		114	
124		115	
125		116	
126		117	
127		118	
128		119	
129		120	
130			

PERSONNEL INJURIES										80
NUMBER					DESCRIPTION					
1	8	0	0	0	40	NA				
7	8	9	11	12						41

LOSS OF OR DAMAGE TO FACILITY		80
TYPE	DESCRIPTION	
19	242 NA	43

PUBLICITY			NRC USE ONLY
ISSUED	DESCRIPTION		
<u>2</u> <u>0</u>	<u>N</u> <u>44</u> <u>NA</u>		<u>45</u>

NAME OF PREPARER Patrick C. Rogers

PHONE: (501) 964-3100

8304280291 830419
PDR ADDCK 05000313
S PDR

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-313/83-007/03X-1

Occurrence Date: 03/08/83

Event Description and Probable Consequences (Continued)

Table 2.3-1. Instrument drift has been reported in LER's (50-313) 74-008, 76-003, 83-003, and 83-004.