

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

327783001)

SYSTEM CODE H B 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMP. SUBCODE P 15		VALVE SUBCODE B 16	
EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 4 8		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0	
ACTION TAKEN E 18		FUTURE ACTION G 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0	
ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER C 7 1 0			

FACILITY STATUS (1) (5) (D) (28) 0 0 0 (29) NA (30) OTHER STATUS
 METHOD OF DISCOVERY (A) (31) Surveillance Review (32) DISCOVERY DESCRIPTION
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 0 0 0 (37) Z (38) NA
 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 0 0 0 (40) NA
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43) Z (42) NA
 PUBLICITY ISSUED DESCRIPTION (45) N (44) NA
 8305030579 830426
 PDR ADOCK 05000327
 S PDR
 NRC USE ONLY

Phone: (615) 870-6422

LER SUPPLEMENTAL INFORMATION

SQRO-50-327/83048

Technical Specification Involved: 3.7.1.1

Reported Under Technical Specification: 6.9.1.13.b

Date of Occurrence: 03/28/83

Time of Occurrence: 1300 CST

Identification and Description of Occurrence:

During the review of surveillance instruction SI-111 on 03/28/83, it was discovered that on 09/11/82, 5 out of 10 main steam safety relief valves (1-RV-1-512, -513, -515, -518, and -521) did not meet required setpoint criteria and during the last half of SI-111 performance on 01/08/83, 2 out of 10 main steam safety relief valves (1-RV-1-525 and -527) did not meet required setpoint criteria.

Conditions Prior to Occurrence:

Unit 1 in mode 3 at 0% power.

Apparent Cause of Occurrence:

The apparent causes were the normal aging of the valve spring and ambient temperature variations.

Analysis of Occurrence:

The 6" x 10" Crosby main steam safety valves (Model No. 6xRx10HA-65-FN) varied from .18% to 1.1% out of acceptable pressure ranges. Slight drifting of the setpoints of this type valve is normal due to ambient temperature variations and valve spring aging. SI-111 did not contain appropriate action to be taken for reportability requirements if a valve failed its setpoint criteria. This resulted in reporting this event after SI review was completed rather than at the time of occurrence.

Corrective Action:

Valve performance will be surveyed during future SI-111 performances to see whether periodic spring replacement would reduce the number and severity of setpoint failures. SI-111 will be revised to clarify action to be taken concerning reportability in the event of main steam safety relief valve performance failure. All failed valves were adjusted within acceptable limits and satisfactorily tested immediately after discovery.

Failure Data:

None.