

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N C B E P 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 1 0 2 8 3 8 0 4 2 0 8 3 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During plant operation, performance of Suppression Pool Level Indicators Operability
0 3 Test, PT-08.1.6, revealed that indicator 2-CAC-LR-2602 showed a level of -31" while
0 4 redundant indicators 2-CAC-LI-2601-1, 2601-3 and the local level indicator showed
0 5 a level of -29". This event did not affect the health and safety of the public.
0 6
0 7

0 8 Technical Specifications 3.3.5.3, 6.9.1.9b
7 8 9 80

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
7 8 9 10 11 12 13 14 15 16
I E 11 B 12 A 13 I N S T R U 14 T 15 Z 16
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
7 8 21 22 23 24 26 27 28 29 30 31 32
8 3 0 0 2 0 3 I 1
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRINT COMP. SUPPLIER COMPONENT MANUFACTURER
33 34 35 36 37 40 41 42 43 44 47
X 18 C 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 N 25 B 0 4 C 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A change in the trickle flow to the wet reference leg of the LR-2602 indicator
1 1 transmitter, LT-2602, caused an incorrect input signal to the indicator. The trickle
1 2 flow was adjusted, LR-2602, Model No. BQ15221, was returned to service, and the PT
1 3 was satisfactorily completed.

1 4
7 8 9 80

1 5 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
E 28 1 0 0 29 NA B 31 Periodic Test

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
Z 33 Z 34 NA NA

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
0 0 0 37 Z 38 NA

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
0 0 0 40 NA

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
Z 42 NA

2 0 PUBLICITY ISSUED DESCRIPTION (45)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
N 44 NA

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521

8305030618 830420
PDR ADOCK 05000324
S PDR

NRC USE ONLY

LER ATTACHMENT - RO #2-83-2

Facility: Unit No. 2

Event Date: January 2, 1983

As a result of an event involving this instrumentation on Unit No. 1, as reported in LER 1-81-07 and a post-TMI requirement, plant modification packages (80-79 and 80-016 for Unit No. 1 and 80-78 and 80-017 for Unit No. 2) have been developed. These modifications will install condensing pots in the reference legs of these instruments in order to increase their accuracy and reliability, and remove the requirement to have flow in their reference legs to ensure they are full.