

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

RECEIVED
NRC

1983 APR 25 PM 1:18

April 15, 1983
ANPP-23514-RQT/BSK

REGION V

50-528
-529
-530

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1

Subject: Interim Report - DER 83-16
A 50.55(e) Potentially Reportable Deficiency Relating to
Diesel Generator Governor and Voltage Regulator Do Not
Automatically Reset From Manual/Test Mode Upon Loss of Power
File: 83-019-026; D.4.3.2


Reference: Telephone Conversation between P. Narbut and R. Tucker on
March 18, 1983

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the
referenced telephone conversation. At that time, it was estimated that a
determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim
Report is attached. It is now expected that this information will be
finalized by May 19, 1983, at which time a complete report will be
submitted.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

EEVB/RQT:db

Attachment

cc: See Attached Page 2

8305030626 830415
PDR ADOCK 05000528
S PDR

IF-27

U. S. Nuclear Regulatory Commission
ANPP-23514-RQT/BSK
April 15, 1983
Page 2

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
G. C. Andognini
J. A. Roedel
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. R. Bynum
P. P. Klute/D. D. Green
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

INTERIM REPORT - DER 83-16
POTENTIAL REPORTABLE DEFICIENCY
ARIZONA PUBLIC SERVICE COMPANY (APS)
PVNGS UNITS 1, 2 & 3

I. POTENTIAL PROBLEM

Specification 13-MM-018, paragraph 4.4.3.3.5 requires that the Diesel Generator governor and voltage regulator manually operated droop mode be automatically reset to the isochronous mode in case of 4.16 kv Class 1E bus undervoltage. While performing a Bechtel Engineering functional check of the Unit 1 Diesel Generator and subsequent review of applicable supplier data, Bechtel Engineering determined that, upon loss of power (LOP), the manual droop mode does not reset to isochronous mode for the governor or the voltage regulator.

II. APPROACH TO AND STATUS OF PROPOSED RESOLUTION

Upon a LOP, the Diesel Generator starts in an emergency mode. The Engineered Safety Features System automatic sequencer simultaneously starts safety-related equipment. If the engine is still in a droop mode, underfrequency and undervoltage could occur. This could potentially result in damage to the actuated safety-related equipment, depending upon the load and droop speed setting. In addition, electric motors will not accelerate properly under the condition of underfrequency/undervoltage. If left uncorrected, the functions of safety-related equipment could be impaired, constituting a safety significant condition representing a significant deficiency in final design.

III. PROJECTED COMPLETION OF CORRECTIVE ACTION
AND SUBMITTAL OF THE FINAL REPORT

Evaluation of this condition and submittal of the Final Report is forecast to be completed by May 19, 1983.