

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC2 2001-100000-100 3411111 4 5

CON'T 01 REPORT SOURCE L 605000316 7031983 50415183 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 DURING SURVEILLANCE TESTING ON THE MAIN TURBINE STOP VALVES ON 3-12-83, THE
03 RESET FUNCTION FOR THE PROXIMITY SWITCH ON STOP VALVE C, TRAIN B, FAILED TO OPERATE
04 IMMEDIATELY. THE TRIP FUNCTION OF THE PROXIMITY SWITCH WAS MADE INOPERABLE FOR
05 REPLACEMENT ON 3-19-83. THIS EVENT IS NON-CONSERVATIVE-WITH RESPECT TO TECHNICAL
06 SPECIFICATION TABLE 3.3-1 ITEM 18.b. THE ACTION REQUIREMENTS WERE MET. THE PUBLIC
07 HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURRENCES INCLUDE: 050-316/78-029,
08 077, 79-008, 81-060.

09 SYSTEM CODE 11A 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE INSITRIU 14 COMP SUBCODE I 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 83 21 EVENT YEAR 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 AT THE PRESENT TIME THE INVESTIGATION IS STILL CONTINUING FOR THIS EVENT. UPON
11 COMPLETION OF THE INVESTIGATION AN UPDATED LER WILL BE SUBMITTED.
12
13
14

15 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

16 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

NAME OF PREPARER R. A. PALMER

616-465-5901