

CONTROL BLOCK:

						(1)
--	--	--	--	--	--	-----

0	1	C	A	S	O	S	3	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4			5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58	

CON'T

0	1																																				
7	8	REPORT SOURCE		L	6	0	5	0	0	0	3	6	2	7	0	4	0	4	8	3	8	0	5	0	3	8	3	9									
				60	61	DOCKET NUMBER												68	69	EVENT DATE						74	75	REPORT DATE						80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While in Mode 5, the fire spray system that protects Radwaste Bldg. Cable Gallery

0 3 spuriously actuated. LCO 3.7.8.2 Action Statement 'a' was entered. Also LCO 3.3.3.7

0 4 Action Statement 'a' was entered since the associated actuation fire detectors were

0 5 inoperable until the system was reset on April 16, 1983. A continuous fire watch

0 6 was established within one hour. The affected fire spray system remained manually

0 7 operable. Health and safety of the public were not affected.

0	8		8
7	8		9

09		A B		X	X	I N S T R U					E	Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
83		83		035		03		L		0			
21		22		23		24		25		26		27	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.	
X		X		Z		Z		0000		N		N	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19		20		21		22		23		24	
33		34		35		36		37		40		41	
18		19											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A review of the Control Operator logs and discussions with fire watch and maintenance
1 1 personnel did not identify any apparent cause of actuation. Compensatory measures
1 2 remained in place until the fire spray system was returned to service on April 16, 1983.
1 3 Initial attempts to reset the deluge valve resulted in valve leakage. As corrective
1 4 action, the proper resetting technique will be provided, in writing, to Operations
7 8 9 FACILITY personnel. METHOD OF 80

FACILITY STATUS: 1 5 G 28
 personnel. % POWER: 0 0 0 29
 OTHER STATUS: NA 30
 METHOD OF DISCOVERY: A 31
 DISCOVERY DESCRIPTION: Operator Observation 32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

44

LOCATION OF RELEASE (36)

NA

45 46 80

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		(37)	Z	(38)
				NA

PERSONNEL INJURIES		80	
NUMBER	DESCRIPTION		
000	40 NA		

8 9 11 12
LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) NA
8305160051 830503
PDR ADPOCK 05000362
S

ISSUED DESCRIPTION (45) NA

NAME OF PREPARED

H. B. RAY

PHONE: 714/492-7700