

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

0 1 N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T

0 1 7 8

REPORT SOURCE

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On April 6, 1983, during routine shift rounds, an operator discovered the 10 Ton Cardox

0 3 System pilot valve in the closed position. The valve is normally locked open to insure

0 4 sufficient pilot gas is available for actuation of the master and master selector

0 5 valves. All low pressure CO2 systems were declared inoperable, and Action Statement

0 6 3.7.10.3a was entered. The valve was opened and locked 26 minutes later, restoring the

0 7 CO2 systems to an operable status. The event constituted operation in a degraded mode

0 8 in accordance with Technical Specification 6.9.1.9b.

7 8 9 80

SYSTEM CODE 0 9		CAUSE CODE A B		CAUSE SUBCODE D		COMPONENT CODE V A L V E X				COMP. SUBCODE F		VALVE SUBCODE D	
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER RO REPORT NUMBER 17		EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 1 2		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0			
21	22	23	24	25	26	27	28	29	30	31	32		
ACTION TAKEN E		FUTURE ACTION G		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N	
33	34	35	36	37	38	39	40	41	42	43	44	PRIME COMP. SUPPLIER A	
18	19	20	21	22	23	24	25	26	27	28	29	COMPONENT MANUFACTURER A 6 0 5	
35	36	37	38	39	40	41	42	43	44	45	46	26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Investigation of the event revealed that the valve may have been left open following

1 1 a system recharging operation on March 4, 1983. No procedure was in effect for

1 2 that operation; and the pilot valve position was not checked in routine system

1 3 surveillance. The procedures were revised accordingly.

1 4

7 8 9
FACILITY STATUS (D) (28) 0 0 0 (29) 13 OTHER STATUS (30) NA 44
METHOD OF DISCOVERY (A) (31) Operator Observation 45 46 80
DISCOVERY DESCRIPTION (32)

7 8 9
ACTIVITY CONTENT
RELEASED OF RELEASE (Z) (33) (Z) (34) NA 44
AMOUNT OF ACTIVITY (35) 45 80
LOCATION OF RELEASE (36)

7 8 9
PERSONNEL EXPOSURES
NUMBER (0) (0) (0) (37) (Z) (38) NA 44
DESCRIPTION (39) 45 80

7 8 9
PERSONNEL INJURIES
NUMBER (0) (0) (0) (40) NA 44
DESCRIPTION (41) 45 80

7 8 9
LOSS OF OR DAMAGE TO FACILITY
TYPE (Z) (42) NA 44
DESCRIPTION (43) 45 80

7 8 9
PUBLICATION
ISSUED (N) (44) NA 44
DESCRIPTION (45) 45 80
NRC USE ONLY

8305160102 830428
PDR ADOCK 05000311
S PDR

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER R. Frahm

PHONE: (609) 935-6000 Ext. 3078