

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE			
7	8	I	E	E		E		I	N	S	T	R	U	B		Z			
		9	10	11	12	13	14	15	16	17	18	19	20						
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
LEX/RO REPORT NUMBER		8	3	--	0	5	7	/	0	3	L	--	0						
21		22		23		24		25		26		27							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
A	Z	Z		Z						Y		N		A		G	0	8	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 5 E 28 1 0 0 29 NA A 31 Operator observation

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA (39)				
7	8	9	11	12	13				

1		9		Z		42		NA		8308180337 830804 PDR ADOCK 05000321 S PDR	
7	8	9	10								

PUBLICATION		ISSUED		DESCRIPTION		NRC USE ONLY														
2	0	N	44	NA																
7	8	9	10																	

PHONE: (912) 367-7851

IE22

590 917-926

NARRATIVE REPORT
FOR LER 50-321/1983-057

LICENSEE : GEORGIA POWER COMPANY
FACILITY NAME : EDWIN I. HATCH
DOCKET NUMBER : 50-321

Tech. Specs. section(s) which requires report:

This 30 day LER is required by Tech. Specs. section 6.9.1.9.b due to the event's showing that the unit was not meeting the requirements of Tech. Specs. Table 3.2-11, reference 14 b).

Plant conditions at the time of the event(s):

The plant was in steady state operation at 2428 MWT (approximately 100% power) when this event occurred.

Detailed description of the event(s):

On 07/11/83, during a control board walkdown, operations personnel noted that the safety relief valve position secondary indicator (1B21-R614) was not indicating properly.

Consequences of the event(s):

Plant operation was continued as permitted by Tech. Specs. Table 3.2-11, note f. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

The safety relief valve position primary indicator (pressure indicator) remained operable during this event.

Justification for continued operation:

The requirements of Tech. Specs. Table 3.2-11, note f were performed (i.e., torus temperature was monitored at least once per shift).

If repetitive, number of previous LER:

This is a non-repetitive event.

Narrative Report for LER 50-321/1983-057

Page Two

Impact to other systems and/or Unit:

This event had no effect on any other Unit 1 system. This event had no impact on Unit 2.

Cause(s) of the event(s):

This event is the result of the safety relief valve's position secondary indicator (i.e., temperature recorder 1B21-R614) failing to operate due to the recorder's having a burned out chart drive motor.

Immediate Corrective Action:

The safety relief valve (SRV) position secondary indicator (1B21-R614) was repaired by replacing the chart drive motor. 1B21-R614 was functionally tested satisfactorily and returned to service on 07/11/83.

Supplemental Corrective Action:

No supplemental corrective action is required.

Scheduled (future) corrective action:

No future corrective action is required.

Action to prevent recurrence (if different from corrective actions):

N/A

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444

USNRC REGION II
ATLANTA, GEORGIA



Georgia Power

Edwin I. Hatch Nuclear Plant

83 AUG 15 A9:43


August 4, 1983
GM-83-717

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-321

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Attached is Licensee Event Report No. 50-321/1983-057. This report is required by Hatch Unit 1 Technical Specifications Section 6.9.1.9.b.


H. C. Nix
General Manager

see
HCN/GBT/djs

xc: R. J. Kelly
G. F. Head
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
S. B. Tipps
R. D. Baker
Control Room
Document Control

OFFICIAL COPY

IE 22
11