

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT
/0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/7/1/1/8/3/ (8) /0/8/0/8/8/3/ (9)
SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On July 11, 12, 16, 17, 24 and 26, 1983, during Unit 1 Mode 1 and 2 operation, 13/
/0/3/ / Individual Rod Position Indicators (IRPI) deviated from the group demand position/
/0/4/ / at various times, by greater than 12 steps. The appropriate Action Statements /
/0/5/ / were satisfied; therefore, the health and safety of the general public were not /
/0/6/ / affected. This event is reportable pursuant to T.S. 3.1.3.2, 3.1.3.3, 3.0.3 and /
/0/7/ / 6.9.1.9.b. /
/0/8/ /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
/0/9/ /I/D/ (11)	/E/ (12)	/E/ (13)	/I/N/S/T/R/U/ (14)	/I/ (15)	/Z/ (16)
LER/RO	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
(17) REPORT NUMBER	/8/3/	/-/	/0/4/6/	/ /	/0/3/
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.
/E/ (18)	/Z/ (19)	/Z/ (20)	/Z/ (21)	/0/0/0/0/ (22)	/N/ (23) /N/ (24) /N/ (25) /W/1/2/0/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The cause of the indicator disagreement was instrument drift caused by detector /
/1/1/ / temperature variations. This is a recurring problem and is generic to Westing- /
/1/2/ / house Analog Position Indication Systems. The I.R.I channels were recalibrated. /
/1/3/ / No further corrective action is required. /
/1/4/ /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
/1/5/ /E/ (28)	/0/4/4/ (29)	/ NA / (30)	/A/ (31)	/ Operator Observation /
ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)	
/1/6/ /Z/ (33)	/Z/ (34)	/ NA /	/ NA /	
PERSONNEL EXPOSURES	NUMBER	TYPE	DESCRIPTION (39)	
/1/7/ /0/0/0/ (37)	/Z/ (38)	/	NA	/
PERSONNEL INJURIES	NUMBER	DESCRIPTION (41)		
/1/8/ /0/0/0/ (40)	/	NA	/	
LOSS OF OR DAMAGE TO FACILITY	TYPE	DESCRIPTION (43)		
/1/9/ /Z/ (42)	/	NA	/	
PUBLICITY	ISSUED	DESCRIPTION (45)	NRC USE ONLY	
/2/0/ /N/ (44)	/	NA	/ / / / / / / / / / / / / / /	

NAME OF PREPARER E. Wayne Harrell

PHONE (703) 894-5151

8308180354 830808
PDR ADOCK 05000338
S PDR

Vepco

USNRC REGION II
ATLANTA, GEORGIA

VIRGINIA ELECTRIC AND POWER COMPANY

NORTH ANNA POWER STATION

P. O. BOX 402

MINERAL, VIRGINIA 23117

83 AUG 10 P 1:06

August 8, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

Serial No. N-83-113
NO/RCS: 11
Docket No. 50-338
License No. NPF-4

Dear Mr. O'Reilly:

Pursuant to North Anna Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following License Event Report applicable to North Anna Unit No. 1.

Report No.


Applicable Technical Specifications

LER 83-046/03L-0

T.S. 6.9.1.9.b

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review.

Very Truly Yours,


E. Wayne Harrell
Station Manager

Enclosures (3 copies)

cc: Document Control Desk (1 copy)
016 Phillips Bldg.
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

IE22 11