

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 1 - 1 1 1 1 1 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 30 31 CAT NO

G 1 T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 0 7 1 0 8 3 9 0 8 0 8 8 5 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 With unit 1 in mode 1 (100% Rx power) at 0810 CDT on 07/10/83, the gaseous effluent

0 3 radiation monitor for the auxiliary building exhaust, 0-RM-90-101, was declared

0 4 inoperable due to loss of flow to the iodine sampler. This event required entry

0 5 into action statement 44 of LCO 3.3.3.10. There was no effect on public health

0 6 and safety. Previous occurrences - none.

0 7

018		7		8		9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE							
M		B		11		E		12		E		13		I N S T R U				14		E		15		Z		16	
9		10		11		12		13		14		15		16		17		18		19		20		21		22	
019		7		8		9		10		11		12		13		14		15		16		17		18		19	
17		LER/RO REPORT NUMBER		EVENT YEAR		23		24		25		26		27		28		29		30		31		32		33	
8		3		—		0		9		6		/		0		3		L		—		0		REVISION NO.		34	
21		22		23		24		25		26		27		28		29		30		31		32		33		34	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER		35		36		37		38		39	
A		X		Z		Z		0		N		N		L		G		0		6		3		40		41	
33		34		35		36		37		38		39		40		41		42		43		44		45		46	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS		27		28		29		30		31		32		33		34		35		36		37		38		39	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Investigation revealed that the sample flow charcoal filter had become stopped up.

The filter was replaced and operation verified at 1005 CDT on 07/11/83. Presently,

the Chemical Lab replaces the filter on a weekly basis which is considered

adequate to prevent recurrence.

1 4
7 8 9

FACILITY STATUS (1) E (28) 1 0 0 (29) NA OTHER STATUS (30)

METHOD OF DISCOVERY (31) B Operator observation DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (33) Z (34) NA LOCATION OF RELEASE (35)

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (36) 0 0 0 (37) Z (38) NA

PERSONNEL INJURIES NUMBER DESCRIPTION (39) 0 0 0 (40) NA

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (41) Z (42) NA

PUBLICITY ISSUED DESCRIPTION (43) N (44) NA PDR ADOCK 05000327 S PDR

NRC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding

Phone: (615) 870-6422

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37402
1750 Chestnut Street Tower II
USNRC REGION II
ATLANTA, GEORGIA

August 8, 1983

83 AUG 15 A9:43

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE
REPORT SQRO-50-327/83096

The enclosed report provides details concerning the inoperability of the
gaseous effluent radiation monitor for the auxiliary building exhaust.
This report is submitted in accordance with Sequoyah unit 1 Technical
Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Sequoyah

~~CONFIDENTIAL~~

IE 22
11