

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 WIKNP1 200-000000-000 341111 4 5  
7 8 9 14 15 25 26 30 37 CAT 38  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CONT

01 L 605000305 7071383 8081283 9  
7 8 60 61 68 69 74 75 80  
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During full power operation, while performing the monthly shield building ventilation  
03 system (SBV) surveillance test, the 1A SBV filter assembly heater failed to energize.  
04 This placed the plant in an LCO per TS 3.6.b.1 which requires both trains of the SBV  
05 system, including filters and heaters, to be operable and is reportable per TS 6.9.2.b (2).  
06 Train "B" of the SBV system was operating at the time and was thus demonstrated operable.  
07 Train "A" was returned to service within T.S. limits. Since only one train is necessary  
08 to meet the safety analysis requirements, there was no effect on the health and safety of  
09 the public.

09 S C 11 E 12 F 13 I N S T R U 14 P 15 Z 16  
9 10 11 12 13 18 19 20  
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
17 8 3 0 1 6 0 3 L 0  
21 22 23 24 26 27 28 29 30 31 32  
 LER:RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
A 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 A 25 F 0 3 0 26  
33 34 35 36 37 40 41 42 43 44 47  
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The heater failed to energize due to a blown fuse in the control circuit. The fuse  
11 was replaced and the required ten hour run for train "A" was successfully completed.  
12 No further action is required.  
13  
14

15 E 28 1 0 0 29 NA B 31 SBV Monthly Surveillance Test 32  
7 8 9 10 12 13 44 45 46 80  
 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
16 Z 33 Z 34 NA NA 36  
7 8 9 10 11 44 45 80  
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 0 0 0 37 Z 38 NA 39  
7 8 9 11 12 13 80  
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 0 0 0 40 NA 41  
7 8 9 11 12 80  
 PERSONNEL INJURIES NUMBER DESCRIPTION

19 Z 42 NA 43  
7 8 9 10 80  
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 N 44 NA 45  
7 8 9 10 80  
 PURGITY ISSUED DESCRIPTION

NAME OF PREPARER S. L. Bernhoft/J. G. Thorgersen

NRC USE ONLY  
 68 69 80  
 (414) 388-2560  
 PHONE: \_\_\_\_\_

8308190303 830812  
 PDR ADUCK 05000305  
 S PDR

## WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

August 12, 1983

Mr. J. G. Keppler, Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305  
Operating License DPR-43  
Reportable Occurrence 83-016/03L-0

In accordance with the requirements of the Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence 83-016/03L-0 is being submitted.

Very truly yours,

*C. W. Giesler for*  
C. W. Giesler  
Vice President - Nuclear Power

js

Attach.

cc - Dir, Office of Inspection & Enforcement  
US NRC, Washington, DC 20555  
Dir, Office of Mgt Info & Program Control  
US NRC, Washington, DC 20555  
INPO Records Center  
Suite 1500, 1100 Circle 75 Parkway  
Atlanta, GA 30339  
Mr. Robert Nelson, NRC Resident Inspector  
RR #1, Box 999, Kewaunee, WI 54216  
Mr. S. A. Varga, Chief  
US NRC, Washington, DC 20555

*IE22*  
AUG 15 1983