

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D C C 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

01 1 L 5 0 5 0 0 0 3 1 5 7 0 7 1 5 8 3 3 0 8 1 2 8 3 9  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

01 2 DURING NORMAL OPERATION, ONE ICE CONDENSER INTERMEDIATE DECK DOOR WAS FOUND FROZEN  
 01 3 SHUT WHICH WAS NON-CONSERVATIVE WITH RESPECT TO T.S. 3.6.5.3. THE ACTION REQUIRE-  
 01 4 MENTS WERE MET. THE DOOR WAS IMMEDIATELY FREED SO THAT IT COULD OPEN IF REQUIRED.  
 01 5 THE REMAINING INT. DECK DOORS WERE OPERABLE. PUBLIC HEALTH AND SAFETY WERE NOT  
 01 6 AFFECTED. PREVIOUS SIMILAR OCCURENCES INCLUDE: 79-036, 79-045, 79-060, 80-010,  
 01 7 80-021, 80-024; DOCKET 050-316, 81-029, 81-038.

01 8 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
 01 9 S B 11 E 12 A 13 X X X X X X 14 Z 15 Z 16  
 01 10 8 3 0 6 7 0 3 L 0  
 01 11 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

01 12 ICE ACCUMULATION AROUND THE DOOR RESULTED IN THE DOOR BEING FROZEN. THE ICE WAS  
 01 13 REMOVED. FURTHER INVESTIGATION REVEALED THAT THE SOURCE OF THE ICE WAS AIR  
 01 14 HANDLING UNIT 3-7A WHICH HAD A FAILED DEFROST HEATER. THE DEFROST HEATER WAS  
 01 15 REPLACED.

01 16 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
 01 17 E 18 0 6 0 29 NA A 31 OPERATOR OBSERVATION  
 01 18 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
 01 19 Z 33 Z 34 NA NA  
 01 20 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
 01 21 0 0 0 37 Z 38 NA  
 01 22 PERSONNEL INJURIES NUMBER DESCRIPTION  
 01 23 0 0 0 40 NA  
 01 24 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
 01 25 Z 42 NA  
 01 26 PUBLICITY DESCRIPTION  
 01 27 N 44 NA

8308190367 830812  
 PDR ADOCK 05000315  
 S PDR

IE22  
 1/1

01 28 NAME OF PREPARER DAVID G. WIZNER PHONE: 616-465-5901  
 01 29 NRC USE ONLY



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

August 12, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,  
the following reports are submitted:

RO 83-067/03L-0

Sincerely,

W.G. Smith, Jr.  
Plant Manager

/cbm

cc: J.E. Dolan  
M.P. Alexich  
R.F. Kroeger  
B. Germano  
E. Swanson/N. DuBry RO:III  
R.C. Callen MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee  
INPO  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

IE22  
11  
AUG 15 1983