

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE:

SUPPLEMENTARY INFORMATION TO
LER 83-068/01 X-1

Mississippi Power & Light Company
Grand Gulf Nuclear Station - Unit 1
Docket No. 50-416

Technical Specification Involved: 3.6.6.2
Reported Under Technical Specification: 6.9.1.12.1

Event Narrative:

This is an update to a previous report submitted on June 16, 1983. The event for which the report was submitted is described in the following paragraphs.

In the fuel handling accident analysis discussed in FSAR Section 15.7.4, a secondary containment ventilation isolation damper closure time of four seconds was used. However, Technical Specification Table 3.6.6.2-1 list the maximum closure time to be five seconds. Also, four secondary containment isolation dampers are not listed in this table. These dampers are M41-F007 and F008 (the drywell/containment purge fan intake isolation dampers) and M41-F036 and F037 (the containment ventilation system exhaust isolation dampers).

The preoperational test showed the closure times to be less than four seconds. However, quarterly surveillance tests, listing a Technical Specification time of five seconds, allowed times to exceed the four seconds. The four second closure times were exceeded on a few occasions.

A Technical Specification change request has been initiated to revise closure times and include the omitted isolation dampers. A Material Non-Conformance Report (MNCR 422-83) was initiated for corrective action to bring the dampers within the four second limit. Surveillance procedures will be revised to reflect these changes. Estimated completion of corrective action is August 30, 1983.

The purpose of this update is to correct a typographical error made in the heading of this page. The Technical Specification involved should have been stated as Technical Specification 3.6.6.2 rather than Technical Specification 3.3.6.2.



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

August 12, 1983

83 AUG 17 48:07

NUCLEAR PRODUCTION DEPARTMENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - Discrepancy
Between Technical
Specification Table and
FSAR
LER 83-068/01 X-1
AECM-83/0456

This letter submits an update to a previous report submitted on June 16, 1983. The event for which the report was submitted occurred on June 3, 1983, when while in Cold Shutdown, a discrepancy between Technical Specification Table 3.6.6.2-1 and FSAR Section 15.7.4.5.2 was identified. The table lists the secondary containment ventilation isolation dampers maximum closure times as 5 seconds, however, the fuel handling accident analysis provided in FSAR Section 15.7.4 uses closure times of 4 seconds. In addition to the above discrepancy, four secondary containment isolation dampers were identified as being omitted from the Technical Specifications. This was reported pursuant to Technical Specification 6.9.1.12.1.

The purpose of this update is to correct a typographical error made on the Supplementary Information page of LER 83-068/01 T-0. In the heading of the page, the Technical Specification involved was incorrectly stated as 3.3.6.2. It should have been 3.6.6.2. Attached is LER 83-068/01 X-1 with Supplementary Information.

Yours truly,

for L. F. Dale
Manager of Nuclear Services

EBS/SHH:sap
Attachment

cc: (See Next Page)

Member Middle South Utilities System

OFFICIAL COPY
7c-22
11

MISSISSIPPI POWER & LIGHT COMPANY

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555