

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 T N S N P 1 7 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 56
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CONT 01 REPORT SOURCE L 6 0 5 10 10 0 3 2 7 7 0 7 1 4 8 3 8 0 8 1 1 8 3 9
2 8 60 61 68 69 74 75 80
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 With unit 1 in mode 1 (100% power, 578 degrees F, 2235 psig) and unit 2 in mode 1
03 (98% power, 577 degrees F, 2235 psig) at 0913 CDT on 07/14/83, while performing
04 SMI-1-SDIB-5, 6900-volt shutdown board 1B-B was deenergized for approximately
05 52 seconds. This event placed the unit in action statement 'a' of LCO 3.8.2.1.
06 There was no effect upon public health and safety. Previous occurrences - none.
07
08
09

SYSTEM CODE E B 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE C K T B R K 14 COMP. SUBCODE A 15 VALVE SUBCODE Z 16
9 10 11 12 13 18 19 20
 LER/RO REPORT NUMBER 17 EVENT YEAR 8 3 SEQUENTIAL REPORT NO. 0 9 0 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32
 ACTION TAKEN H 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER L 25 COMPONENT MANUFACTURER I 2 0 2
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Personnel failed to reset device 86S1B before replacing PK trip cut-out blocks
11 as required in the procedure. Operator reset the 86 device after the board was
12 deenergized and D/G reenergized the board. Appropriate disciplinary action was
13 taken. No procedure changes were necessary. No further action is required.
14

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Operator observation 32
7 8 9 10 12 13 44 45 46 80
 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 44 45 80
 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 11 12 13 80
 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 11 12 13 80
 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 12 80
 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 80

8308190391 830811
 PDR ADOCK 05000327
 S PDR

IE 22

Name of Preparer: G. E. Duggin /M. R. Harding

Phone: (615) 870-6422

NRC USE ONLY

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
1750 Chestnut Street Tower II

USNRC REGION II
ATLANTA, GEORGIA

August 11, 1983

83 AUG 17 A8:07

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE
REPORT SQRO-50-327/83090

The enclosed report provides details concerning the deenergizing of
6900-volt shutdown board 1B-B while it was being returned to normal
operation after performing SMI-1-SD1B-5. This report is submitted in
accordance with Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Sequoyah

OFFICIAL COPY

IE 22

1/1