

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MDCCN1200-00000-0034111145

LICENSEE CODE

LICENSE NUMBER

LICENSE TYPE

CAT 58

CON'T

REPORT SOURCE

01 L605000317704268380505839

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During Mode 5 operation at 2014 while raising RCS pressure, a Power Op-  
03 erated Relief Valve (PORV), ERV-404 opened. It was immediately isolated  
04 by shutting its upstream isolation valve (T.S. 3.4.9.3). While trouble-  
05 shooting the problem with ERV-404, at 2150 a short circuit caused a loss  
06 of control power to ERV-402, rendering it inoperable. Control power was  
07 restored to ERV-402 by 2207. RCS pressure was lowered to below the re-  
08 set point, and ERV-404 unisolated by 2230. Similar events: none.

SYSTEM CODE

CAUSE CODE

CAUSE SUBCODE

COMPONENT CODE

COMP. SUBCODE

VALVE SUBCODE

09 CB11 A12 A13 ZZZZZZ14 Z15 Z16

LER/RO REPORT NUMBER

EVENT YEAR

SEQUENTIAL REPORT NO.

OCCURRENCE CODE

REPORT TYPE

REVISION NO.

17 83 019 01 T 0

ACTION TAKEN

FUTURE ACTION

EFFECT ON PLANT

SHUTDOWN METHOD

HOURS

ATTACHMENT SUBMITTED

NPRD-4 FORM SUB.

PRIME COMP. SUPPLIER

COMPONENT MANUFACTURER

H18 H19 Z20 Z21 0000 Y23 N24 Z25 Z999926

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The cause of the actuation of ERV-404 was a failure of the Control Room  
11 Operator to monitor RCS pressure carefully enough. The short circuit in  
12 the ERV-402 control circuitry was due to technician error. Personnel in-  
13 volved in this event have been counselled. All operators and instrument  
14 maintenance technicians will be informed of the details of this event.

FACILITY STATUS

% POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

15 G28 00029 N/A A31 Operator Observation

ACTIVITY CONTENT

RELEASED OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

16 Z33 Z34 N/A N/A

PERSONNEL EXPOSURES

NUMBER

TYPE

DESCRIPTION

17 00037 Z38 N/A

PERSONNEL INJURIES

NUMBER

DESCRIPTION

18 00040 N/A

LOSS OF OR DAMAGE TO FACILITY

TYPE DESCRIPTION

19 Z42 N/A

PUBLICITY

ISSUED DESCRIPTION

20 N44 N/A

8305230513 830505  
PDR ADOCK 05000317  
S PDR

NRC USE ONLY

LER NO. 83-19/1T  
DOCKET NO. 50-317  
LICENSE NO. DPR 53  
EVENT DATE 04-26-83  
REPORT DATE 05-05-83  
ATTACHMENT

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (CONT'D)

During Mode 5 operation at 2014 while raising RCS pressure, a Power Operated Relief Valve (PORV) opened. With RCS temperature approximately 198°F, RCS pressure was being raised to about 400 psig. When the plant computer indicated a RCS pressure of about 400 psig, ERV-404 opened (its setpoint is 425 psig). ERV-404 was immediately isolated by shutting its upstream valve (T.S. 3.4.9.3). It was then discovered that plant computer indication of RCS pressure was reading about 30 psig less than PIC-103-1 indication. A signal from PIC-103-1 controls ERV-404. While troubleshooting the problem with ERV-404 at 2150, a short circuit caused a loss of control power to ERV-402, rendering a second PORV inoperable (T.S. 3.4.9.3). Control power was restored to ERV-402 by 2207. RCS pressure was lowered to below the ERV-404 reset point. By 2230, both PORVs were in service in MPT enable.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

The cause of the actuation of ERV-404 was a failure of the Control Room Operator to closely monitor pressure indication on PIC-103-1 while attempting to raise RCS pressure to a point near the PORV lift setpoint. The short circuit and subsequent loss of control power to ERV-402 were due to technician error. The personnel involved in this event have been counselled. All operators and all instrument maintenance technicians will be informed of the details of this event.