

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	0	H	D	B	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5			
7	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT 58	

60	61	DOCKET NUMBER
----	----	---------------

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 (NP-33-83-20) On 4/7/83 it was determined that the amplifier of the startup level
0 3 transmitter LT-SP9A3 for Steam Generator (SG) 1-2 had failed. This failure would pre-
0 4 vent Auxiliary Feedwater (AFW) Pump 1-2 from controlling SG level in auto-essential
0 5 from a level signal from SG 1-2 since the pumps governor would be driven to the low
0 6 speed stop and held there. This placed the unit in the action statement of Tech Spec
0 7 3.7.1.2. There was no danger to the health and safety of the public or station per-
0 8 sonnel. AFW Train 1-1 was operable and AFW 1-2 could have been operated in manual.

7 8

SYSTEM CODE
C 9 10

CAUSE CODE
E 11

CAUSE SUBCODE
G 12

COMP. SUBCODE
T 15

VALVE SUBCODE
Z 16

COMPONENT CODE
I N S T R U 13 14 16

SEQUENTIAL REPORT NO.
0 1 6 24 26

OCCURRENCE CODE
0 3 28 29

REPORT TYPE
X 30

REVISION NO.
1 32

LER/RO REPORT NUMBER
17

EVENT YEAR
8 3 21 22

ACTION TAKEN
A 18 33

FUTURE ACTION
Z 19 34

EFFECT ON PLANT
Z 20 35

SHUTDOWN METHOD
Z 21 36

HOURS
0 0 22 37 40

ATTACHMENT SUBMITTED
Y 23 41

NPRD-4 FORM SUB.
N 24 42

PRIME COMP. SUPPLIER
N 25 43

COMPONENT MANUFACTURER
B 0 4 5 26 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause was a component failure within the amplifier. On 4/9/83 at 1830 hours under

1 1 Maintenance Work Order 83-2544, the amplifier was replaced. AFW Train 1-2 was de-

1 2 clared operable, removing the unit from the action statement.

1 3

1 4

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
1	5	E	28	0	9	9	29	NA	A	31	Operator observation	32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 34 NA

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

44

LOCATION OF RELEASE (36)

45 80

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION (39)						
1	7	0	0	0	(37)	2	(38)	NA		


PERSONNEL INJURIES		80
NUMBER	DESCRIPTION	
41		

7 9 11 12 NA 8305260293 830517 80
LOSS OF OR DAMAGE TO FACILITY (43) PDR ADICK 05000346

TYPE		DESCRIPTION		PDR NUMBER	
1	9	Z	NA	S	PDR

ISSUED (44) NA (45) PUBLICITY DESCRIPTION NRC USE ONLY

DMB



May 17, 1982

Log No. K83-725
File: RR 2 (NP-33-83-20)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Revision 1 to Licensee Event Report 83-016, (NRC Form 366). The LER form has been revised to indicate the correct code in block 24, NPRD-4 Form Submitted. There has been no change to the supplemental information pages of this report.

Please replace your previous copies of this LER form with the attached revision.

Yours truly,

T.D. Murray/smq

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Tom Peebles
NRC Resident Inspector
Encl: 1 copy

IE22

MAY 20 1983