

CONTROL BLOCK:

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	IA 0 A C 1	2	0 0 0 - 0 0 0 0 0 0 - 0 0 0	3	4	1 1 1 1 1 1 1 1	4	5	
LICENSEE CODE		LICENSE NUMBER		LICENSE TYPE		CAP 56			
CONT									
01	L	6	0 5 0 0 0 3 3 1	7	0 8 0 3 8 3	8	0 8 1 7 8 3	9	
REPORT SOURCE		DOCKET NUMBER		EVENT DATE		REPORT DATE			
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)									
02	During normal operation, while conducting surveillance testing, it was f								
03	ound that the RCIC discharge pressure indicator was not indicating prope								
04	rly. Since the surveillance test could not be completed due to this prob								
05	lem, RCIC was declared inoperable. A 7 day LCO was declared IAW T.S. 3.5								
06	L.E.2. While testing redundant systems, test of HPCI could not be complet								
07	ed (See LER 83-028). ADS, CS, and LPCI were proven operable. No effect o								
08	n health and safety of public. No previous similar occurrences.								
09									
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMP. SUBCODE		VALVE SUBCODE	
C E 11		E 12		E 13		T 15		Z 16	
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
8 3		0 2 7		0 3		L		0	
LER/RO REPORT NUMBER		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.	
E 18		Z 21		0 0 0 0		N 23		N 24	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
E 18		Z 19		Z 20		N 25		G 0 8 0	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)									
10	The pressure transmitter for the faulty indication was out of calibratio								
11	n. The transmitter was calibrated and the surveillance testing of the RC								
12	IC completed satisfactorily on 8/3.								
13									
14									
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
E 15		0 9 6		NA		B 31		Routine Testing	
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
Z 16		Z 33		NA		NA			
PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICATION			
NUMBER TYPE DESCRIPTION		NUMBER DESCRIPTION		TYPE DESCRIPTION		ISSUED DESCRIPTION			
0 0 0 37 Z 38 NA		0 0 0 40 NA		Z 42 NA		N 44 NA			
<div style="display: flex; justify-content: space-between;"> <div> NAME OF PREPARER Daniel R. Kibler </div> <div> 8308260046 830817 PDR ADOCK 05000331 S PDR </div> <div> NRC USE ONLY </div> </div>									
<div style="display: flex; justify-content: space-between;"> <div> PHONE: 319-851-7306 </div> <div> </div> </div>									

Iowa Electric Light and Power Company

August 17, 1983
DAEC-83-675

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Duane Arnold Energy Center
Docket No. 50-331
Op. License DPR-49
Licensee Event Report No. 83-027
(30-day)

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications, Section 6.11.2.b(2), and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report.

Very truly yours,

BR York for

Daniel L. Mineck
Plant Superintendent - Nuclear
Duane Arnold Energy Center

DLM/DRK/pf

attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector - DAEC

File A-118a

AUG 19 1983