

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | | L | L | S | C | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 0 | 0 | 0 | 4 | | 5

7 8 9 14 15 25 26 30 37 38

LICENSE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT

REPORT SOURCE L 5 0 5 0 0 0 3 7 3 7 0 7 1 1 9 8 3 3 0 8 1 6 6 3 9

60 61 DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 1030 on July 19 1983 the "LPCS Injection Valve Permissive" alarm was up on the 1H13-P601 panel with the reactor pressure at 600 psig. Alarm should be clear at Rx pressure greater than 500 psig. Press. switch 1B21-413A was found to be continuously in the alarm position. The LPCS injection valve had an open permissive signal because the LPCS check valve seats well, inadvertent opening of the injection valve would not have caused an intersystem LOCA. LPCI A was still operable since its own pressure switch was functioning properly. HPCS, the three LPCI, and RCIC were all operable. Safe operation of the unit was maintained at all times.

7 8 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
0 9		S F		E		E		I N S T R U				S		Z	
7 8		9 10		11		12		13 14 15 16 17 18				19		20	
		EVENT YEAR				SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
(17) LER/RO REPORT NUMBER		8 3		—		0 7 8		0 3		L		0			
21 22		23		24		25 26 27		28 29		30		31 32			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPR/RO FORM SUBM.			
B		Z		Z		Z		0 0 0 0		Y		N			
18 19		20		21		22		23		24		25			
33 34		35		36		37 38 39 40		41		42		43			
5 3 8 2															
44		45		46		47		48		49		50			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)	
1 0	The cause of the occurrence was that the microswitch in the pressure switch was stuck closed. The pressure switch was freed and exercised, recalibrated and functionally
1 1	
1 2	checked, and declared operable at 1200 on July 19, 1983.
1 3	

1 4		7 8 9		FACILITY STATUS		% POWER		OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (22)	
1 5		8 (28)		0 0 0 (29)		NA		A (31)		Work Request L26101			
7 8 9		10 11 12		13		44		45		46		80	
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY (35)				LOCATION OF RELEASE (36)					
1 6		Z (33)		Z (34)		NA		NA					
7 8 9		10 11 12		13		44		45		46		80	

PERSONNEL EXPOSURES		TYPE		DESCRIPTION	
NUMBER					
1	7	0	0	0	NA
		17	Z	38	

[illegible]

7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY (42)
TYPE DESCRIPTION NA
IE22

1 9 2 (42) 7 8 9 10
PUBLICATION (45)
ISSUED DESCRIPTION 8303260086 830816
PDR ADONCK 05000373 NRC USE ONLY

7 8 9 10

NAME OF PREPARER

8303260086 830816
PDR ADDCK 05000373
S PDR

Paul S. Watford

NRC USE ONLY

PHONE:

815/357-6761 Ext 323

- I. LER NUMBER: 83-078/03L-0
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 050-373
- IV. EVENT DESCRIPTION:

At 1030 on July 19, 1983, the LPCS Injection Valve Permissive alarm was up on the 1H13-P601 panel with the reactor pressure at 600 psi. Alarm should be clear at reactor pressure greater than 500 psig. The plant was in Mode 3, Shutdown. The LPCS system was declared inoperable.

V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

Technical Specification 3.3.3 requires that the Division 1 Trip System for LPCS Injection Valve Reactor Pressure-Low Permissive to have a minimum of one operable channel per trip or declare the associated ECCS inoperable. HPCS, the three LPCI, and RCIC systems were all operable.

For the LPCS alarm to sound, two signals are required: one from the Nuclear Boiler and one from the LPCS line between the Injection Valve and the LPCS Check Valve. Both switches have the same setpoints. When the reactor pressure is greater than 500 psig, both pressure switches' relay contacts should open, the injection valve would be interlocked closed, and no alarm would sound. However, one of the boiler pressure switches stayed closed. In addition, since the LPCS injection check valve seats well, the pressure switch between the check valve and the LPCS injection valve lags behind the reactor pressure and this had not increased to the 500 psig setpoint.

Division 1 LPCS/LPCI A Injection Valve Reactor Pressure Low Interlock Switch A would have allowed the LPCS injection valve to open since it had an open permissive signal. However, since LPCS check valve seats well, inadvertent opening of the injection valve would not have caused an intersystem LOCA. 1B21-N413A did affect LPCI A but LPCI A was still operable because its own pressure switch 1E12-N413A was functioning properly and sensing 600 psig reactor pressure.

Prior to startup, a work request was written; the inoperable pressure switch was repaired and returned to operable status the same day. This was the first occurrence of this event. Safe operation of the unit was maintained.

VI. CAUSE:

The cause of this occurrence was the microswitch in the pressure switch was stuck closed. The repaired microswitch was in pressure switch, Model #FN6, and was manufactured by Static-O-Ring.

VII. CORRECTIVE ACTION:

Work Request L26101 was written to repair the microswitch. The pressure switch was freed and exercised, recalibrated and functionally checked per approved station procedure LIS-NB-18, and declared operable at 1200 on July 19, 1983.



Commonwealth Edison
LaSalle County Nuclear Station
Rural Route #1, Box 220
Marseilles, Illinois 61341
Telephone 815/357-6761

August 16, 1983

James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Sir:

Reportable Occurrence Report #83-078/03L-0 Docket #050-373 is being submitted to your office in accordance with LaSalle County Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

CE Sargent
for G. J. Diederich
Superintendent
LaSalle County Station

RHH/GW/bej

Enclosure

xc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U. S. NRC Document Management Branch
Inpo-Records Center
File/NRC

AUG 19 1983

JE22
11