

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C M G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT

01 REPORT SOURCE L 5 0 5 0 0 0 3 6 9 7 0 7 1 4 8 3 8 0 8 1 7 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Mode 1 (Unit 1) and Mode 5 (Unit 20, investigation of a "VC/YC Chiller
03 B Trouble" alarm resulted in control area ventilation system (VC) Train B being
04 declared inoperable due to a low refrigerant temperature trip of control room
05 area chiller B which failed to reset. This violates T.S.3.7.6 which is reportable
06 per T.S.6.9.1.11(b) and similar to RO's 369/81-44 and 83-48. Because of redundant
07 trains the ability of the VC system to maintain the control room area at permis-
08 sible temperatures was not compromised. Health and safety of the public were
09 unaffected.

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
S G 11 E 12 X 13 I N S T R U 14 C 15 Z 16
17 LER/NO REPORT NUMBER 8 3 18 0 5 6 19 0 3 20 L 21 0 22 0 23 X 9 9 9 24
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 X 19 Z 20 Z 21 0 0 0 0 22 N 23 N 24 L 25 X 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A loose flange on the suction side of the compressor resulted in slightly low
11 refrigerant level. Also, Channel B cooler CR-AHU-2 temperature regulator valve
12 1YC-113 was discovered to be malfunctioning due to an improper signal from its
13 controller, bypassing the CR-AHU-2 coils (this may have partially caused RO-369/
14 83-48). The loose flange was tightened and refrigerant added. The controller
15 (MCC Powers 163-3320, Series 200) will be properly set up and calibrated.

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
X 28 1 0 0 29 Mode 1(U1)&5(U2) A 31 Control Room Indications/Alarm

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 32 Z 34 N/A N/A

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 N/A

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 N/A

20 PUBLICITY ISSUED DESCRIPTION 45
N 44 N/A

NAME OF PREPARER Phillip B. Nardoci

PHONE (704) 373-7432

USNRC REGION II
DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 29242

TELEPHONE
(704) 373-4531

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

AUG 23 1980
89 AUG 23 49:48

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Units 1 and 2
Docket Nos. 50-369 and 50-370
LER/RO-369/83-56

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-56. This report concerns T.S. 3.7.6, "Two independent control area ventilation systems shall be operable". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

H.B. Tucker
Hal B. Tucker

PBN:jfw
Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY

IE 22
11