

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 F I L S L S 2 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 5  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T  
 0 1 REPORT SOURCE L 5 0 5 0 0 0 3 8 9 7 0 7 1 8 8 3 8 0 9 1 7 8 3 9  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30  
 SOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
 0 2 While operating at 50% power the "A" QSPDS failed. This is not in accord-  
 0 3 ance with T.S. 3.3.3.6. The "B" QSPDS continued to perform satisfactorily.  
 0 4 The "A" QSPDS was back in service the next day well within Tech. Spec.  
 0 5 requirements. At no time were the health and safety of the public in  
 0 6 jeopardy. This is the first LER of this type.  
 0 7  
 0 8  
 0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
 0 9 I D 11 E 12 E 13 I N S T R U 14 I 15 4 16  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION  
 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
 8 3 0 4 0 3 L 0  
 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP SUPPLIER COMPONENT MANUFACTURER  
 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47  
 A Z Z Z 0 0 0 0 N N N E 1 4 6  
 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
 1 0 Investigation revealed that the plasma display unit had failed. The failed  
 1 1 unit was removed and a new one installed. The new unit was then satis-  
 1 2 factorily tested and placed in service.  
 1 3  
 1 4  
 1 5

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
 1 5 B 3 5 0 NA A 31 Operator Observation  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
 1 6 Z 33 Z 34 NA NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
 1 7 0 1 0 0 Z 38 NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

PERSONNEL INJURIES NUMBER DESCRIPTION  
 1 8 0 1 0 0 40 NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
 1 9 Z 42 NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

PUBLICITY ISSUED DESCRIPTION  
 2 0 N 44 NA  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

NAME OF PREPARER Joseph P. Brannin PHONE 465-3550 (3427)

JE 22

USNRC REGION II  
ATLANTA, GEORGIA

83 AUG 23 A9: 47



August 17, 1983  
PNS-LI-83-560-1

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street N.W., Suite 2900  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 50-389-83-40

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: JULY 18, 1983

TECHNICAL SPECIFICATION 3.3.3.6

"A" QSPDS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

*JWW*  
for J. W. Williams, Jr.  
Vice President  
Nuclear Energy

JWW/JEM/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Harold F. Reis, Esquire  
File 933.1 SL

OFFICIAL COPY  
IE 2211