

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	A	P	P	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT		58

CON T

REPORT SOURCE: L 6 0 5 0 - 0 2 9 3 7 0 7 1 3 8 3 8 0 8 0 9 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On July 13, 1983 the latch on fire door #102 was found inoperable , and on
0 3 | July 15, 1983 the latch on door #105 was found inoperable. In both cases fire
0 4 | watch patrols were initiated in accordance with Tech. Spec. 3.12.F and Mainten-
0 5 | ance Requests issued. These events created no threat to the public health and
0 6 | safety.
0 7 |
0 8 |

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE			
0	9	A	B	E	B	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22		
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17	8	3	—	0	4	1	/	0	3	L	—	0					
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A	Z	Z	Z	Z	Z	0	0	0	0	N	N	Z	X	9	9	9	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 One latch mechanism required adjustment, the other was replaced, in kind.

1 1 Following these repairs, both doors were tested satisfactorily and the fire

1 2 watch patrols terminated. These failures were due to normal wear and current

1 3 station procedures are considered adequate to monitor the status of T.S.

1 4 related fire doors.

FACILITY STATUS (1) 5 (2) E (3) 28 (4) 1 (5) 0 (6) 0 (7) 29 (8) N/A (9) 30
 METHOD OF DISCOVERY (1) A (2) 31 (3) Observation (4) 32
 DISCOVERY DESCRIPTION (1) 32
 ACTIVITY CONTENT RELEASED OF RELEASE (1) 1 (2) 6 (3) Z (4) 33 (5) Z (6) 34 (7) N/A (8) 35
 AMOUNT OF ACTIVITY (1) 35
 LOCATION OF RELEASE (1) N/A (2) 36

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION
1	7	0	0	0	(37) Z (38) N/A

PERSONNEL INJURIES		NUMBER		DESCRIPTION		(41)	
1	8	0	0	0	(40)	N/A	

LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)

7 8 9 10 N/A

PUBLICITY
ISSUED DESCRIPTION (45)

NRC USE ONLY

2 0 N 44 N/A

NAME OF PREPARER

G. G. Whitney

PHONE (617) 746-7900

8308310345 830809
PDR ADCK 05000293
S PDR

BOSTON EDISON COMPANY
800 BUYLSTON STREET
BOSTON, MASSACHUSETTE 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

August 9, 1983

BECO. #83-212

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406


Docket No. 50-293
License DPR-35

Dear Sir:

The attached License Event Report 83-041/03L-0, "Fire Door Latches", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.b.

If there are any questions on this subject, please contact us.

Respectfully submitted,


William D. Harrington

WDH/mg

Enclosure: LER 83-041/03L-0

cc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECo. LER distribution

IE22
1/1