

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)1 1 C A S O S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 6 2 7 0 7 1 7 8 3 8 0 8 1 6 8 3 9  
7 8 DOCKET NUMBER 48 49 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 With Unit 3 in Mode 4, at 1230 the outer containment airlock door jammed in the  
0 3 open position. In accordance with Action Statement 'a' of LCO 3.6.1.3, the inner  
0 4 airlock door was maintained in the closed position while repairs were made on  
0 5 the inoperable door. The Action Statement was satisfied at 1430 when repairs on  
0 6 the door were complete. Since the inner airlock door remained operable through-  
0 7 out this incident, the health and safety of the public were not affected. See  
0 8 also Unit 2 LER 82-064.

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
S D 11 E 12 B 13 P E N E T R 14 A 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER/NO REPORT NUMBER 8 3 21 22 SEQUENTIAL REPORT NO. 0 5 0 23 24 OCCURRENCE CODE 0 3 25 26 REPORT TYPE L 27 28 REVISION NO. 0 29 30  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFRD-A FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
B 18 F 19 Z 20 Z 21 0 0 0 0 22 N 23 N 24 N 25 C 3 1 0 26  
33 34 35 36 37 38 39 40 41 42 43 44 45

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event was a broken cam follower on the personnel airlock door.  
1 1 Heavy personnel traffic through this door has occurred since Unit 3 initial fuel  
1 2 load and is considered a major factor in the failure of the door. As immediate  
1 3 corrective action, the cam follower was replaced. A design change is  
1 4 currently being developed to prevent similar failures in the future.

1 5 FACILITY STATUS B 28 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 41 DESCRIPTION NA 42  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 43 DESCRIPTION NA 44  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
2 0 PUBLICITY ISSUED DESCRIPTION N 44 45 NA 46  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8309010058 830816  
PDR ADOCK 05000362  
S PDR

NAME OF PREPARER

H. B. RAY

PHONE (714) 492-7700

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION  
P.O. BOX 128  
SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY  
STATION MANAGER

August 16, 1983

RECEIVED  
MTC

SCE

1983 AUG 18 PM 12:17

REGIONAL

TELEPHONE  
(714) 392-7700

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. J.B. Martin, Regional Administrator


Dear Sir:

Subject: Docket No. 50-362  
30-Day Report  
Licensee Event Report No. 83-050  
San Onofre Nuclear Generating Station, Unit 3

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.6.1.3 associated with the containment airlocks. Enclosed LER 83-050 addresses this event, including corrective actions to prevent recurrence.

If there are any questions regarding the above, please contact me.

Sincerely,



Enclosure: LER No. 83-050

11  
IE-22  
83-334

August 16, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)  
J.P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission  
Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)