

## LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/2/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

/0/1/ REPORT /L/ (6) /0/5/C/0/0/3/3/9/ (7) /0/7/3/0/8/3/ (8) /0/8/2/4/8/3/ (9)  
 SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On July 30, 1983, with Unit 2 in Mode 3 and on July 31 and August 3, 1983 during /  
 /0/3/ / Unit 2 startup and subsequent operation at 100 percent power, 3 Individual Rod /  
 /0/4/ / Position Indicators (IRPI) deviated from the group demand position at various /  
 /0/5/ / times by greater than 12 steps. Since the appropriate Action Statements were /  
 /0/6/ / satisfied, the health and safety of the public were not affected. This event is /  
 /0/7/ / reportable pursuant to T.S. 3.1.3.2, 3.1.3.3 and 6.9.1.9.b. /  
 /0/8/ /

SYSTEM CAUSE CAUSE COMP. VALVE  
 CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE

/0/9/ /I/D/ (11) /E/ (12) /E/ (13) /I/N/S/T/R/U/ (14) /I/ (15) /Z/ (16)  
 LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION  
 (17) REPORT NO. TYPE NO.  
 NUMBER /8/3/ /-/ /0/6/5/ /-/ /0/3/ /L/ /-/ /0/

ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT  
 TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER

/E/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /N/ (23) /N/ (24) /N/ (25) /W/1/2/0/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The cause of the indicator disagreement was instrument drift caused by detector /  
 /1/1/ / temperature variations. This is a recurring problem and is generic to Westing- /  
 /1/2/ / house Analog Position Indication Systems. The IRPI channels were either properly /  
 /1/3/ / recalibrated and returned to service or the reactor trip breakers were opened. /  
 /1/4/ / No further corrective action is required. /

FACILITY METHOD OF  
 STATUS %POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION (32)  
 /1/5/ /G/ (28) /0/0/0/ (29) / NA / (30) /A/ (31) / Operator Observation /

ACTIVITY CONTENT  
 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

/1/6/ /Z/ (33) /Z/ (34) / NA / / NA /

PERSONNEL EXPOSURES  
 NUMBER TYPE DESCRIPTION (39)

/1/7/ /0/0/0/ (37) /Z/ (38) / NA /

PERSONNEL INJURIES  
 NUMBER DESCRIPTION (41)

/1/8/ /0/0/0/ (40) / NA /

LOSS OF OR DAMAGE TO FACILITY (43)  
 TYPE DESCRIPTION

/1/9/ /Z/ (42) / NA /

PUBLICITY

ISSUED DESCRIPTION (45)

/2/0/ /N/ (44) / NA /

NRC USE ONLY

NAME OF PREPARER E. Wayne Harrell

PHONE (703) 894-5151

8309060093 830824  
 PDR ADOCK 05000339  
 S PDR

**Vepco**

USNRC REGION II  
ATLANTA, GEORGIA

VIRGINIA ELECTRIC AND POWER COMPANY

83 AUG 29 P2:04  
NORTH ANNA POWER STATION

P. O. BOX 402

MINERAL, VIRGINIA 23117

August 24, 1983

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 2900  
Atlanta, Georgia 30303

Serial No. N-83-125  
NO/JCR: 11  
Docket No. 50-339  
License No. NPF-7

Dear Mr. O'Reilly:

Pursuant to North Anna Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following License Event Report applicable to North Anna Unit No. 2.

Report No.


Applicable Technical Specifications

LER 83-065/03L-0

T.S. 6.9.1.9.b

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review.

Very Truly Yours,



E. Wayne Harrell  
Station Manager

Enclosures (3 copies)

cc: Document Control Desk (1 copy)  
016 Phillips Bldg.  
U.S. Nuclear Regulatory Commission  
Washington, D. C. 20555

OFFICIAL COPY

IE 22  
11