

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7 8 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE		80	
0	9	I	E	11	E	12	E	13	I	N	S	T	R	U	14	R	15	Z	16
7	8	9	10		11	12	13		14	15	16	17	18	19	20				
(17) LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
8		3		0		7		3		0		3		L		0			
21		22		23		24		25		26		27		28		29		30	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
B	18	Z	19	Z	20	Z	21	0	p	p	p	22	Y	23	N	24	A	25	L
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	28	1	0	0	29	NA	A	31	Performing Maintenance			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	000	Z	NA

PERSONNEL INJURIES

NUMBER		DESCRIPTION
1	0	NA

8309060198 830818
888 4886K 05000321

1	9	Z	(42)	NA	LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION	(43)	PDR ADUCK 03000521 S PDR
---	---	---	------	----	---	------	-----------------------------

7	8	9	10	80	
PUBLICITY			NRC USE ONLY		
ISSUED	DESCRIPTION		45		

2	0	N	(44)	NA																											
7	8	9	10	68															69	80											

NAME OF PREPARER S. B. Tipps

PHONE: (912) 367-7851

Narrative Report for LER 50-321/1983-073
Page Two

Impact to other systems and/or Unit:

This event had no effect on any other Unit 1 system. This event did not affect Unit 2.

Cause(s) of the event(s):

This event is the result of the failure of the pressure recorder's amplifier circuit board.

Immediate Corrective Action:

The drywell and torus pressure recorder 1T48-R608 was repaired by replacing the failed amplifier circuit board. This recorder was functionally tested satisfactorily and returned to service on 07/24/83.

Supplemental Corrective Action:

No supplemental corrective action was required.

Scheduled (future) corrective action:

No future corrective action is required.

Action to prevent recurrence (if different from corrective actions):

N/A

NARRATIVE REPORT
FOR LER 50-321/1983-073

LICENSEE : GEORGIA POWER COMPANY
FACILITY NAME : EDWIN I. HATCH
DOCKET NUMBER : 50-321

Tech. Specs. section(s) which requires report:

This 30-day LER is required by Tech. Specs. section 6.9.1.9.b due to the event's showing that the unit was not meeting the requirements of Tech. Specs. Table 3.2-11, items 4 and 9.

Plant conditions at the time of the event(s):

On 07/23/83, the plant was in steady state power operation at 2432 MWT (approximately 100% power) when this event occurred.

Detailed description of the event(s):

On 07/23/83, while performing maintenance on the drywell and torus pressure recorder (1T48-R608), maintenance personnel discovered that the pressure recorder was reading erratically. This made the recorder inoperable which is a failure to meet the requirements of Tech. Specs. Table 3.2-11, items 4 and 9.

Consequences of the event(s):

Plant operation continued under a 30-day LCO permitted by Tech. Specs. Table 3.2-11, note c for items 4 and 9. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

The redundant drywell and torus pressure recorder (1T48-R609) remained operable during this event.

Justification for continued operation:

Plant operation was continued as permitted by Tech. Specs. Table 3.2-11, note c for items 4 and 9.

If repetitive, number of previous LER:

This is a non-repetitive event.

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444

USNRC REGION II
ATLANTA, GEORGIA



Georgia Power

Edwin I. Hatch Nuclear Plant

83 AUG 30 A10:33


August 18, 1983
GM-83-802

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-321

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Attached is Licensee Event Report No. 50-321/1983-073. This report is required by Hatch Unit 1 Technical Specifications Section 6.9.1.9.b.


H. C. Nix
General Manager

SB1
HCN/SBT/djs

xc: R. J. Kelly
G. F. Head
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
S. B. Tipps
R. D. Baker
Control Room
Document Control

OFFICIAL COPY
1022