

## U.S. NUCLEAR REGULATORY COMMISSION

## LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT  
/0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/8/0/3/8/3/ (8) /0/8/2/4/8/3/ (9)  
SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On August 3, 1983, with Unit 1 at 100 percent power, Fire Door S54-8 failed to /  
/0/3/ / automatically reclose. A pin in the double door sequencing device backed out /  
/0/4/ / causing the sequencing bar to hold one door open. The pin was pushed back into /  
/0/5/ / place and door operation was checked. The door operated satisfactorily. The /  
/0/6/ / Action Statement of the applicable LCO (T.S. 3.7.15) was met. The public health /  
/0/7/ / and safety were not affected. This event is reportable pursuant to /  
/0/8/ / T.S. 6.9.1.9.b. /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE	
/0/9/	/A/B/ (11)	/E/ (12)	/B/ (13)	/X/X/X/X/X/X/ (14)	/Z/ (15)	/Z/ (16)
	LER/RO	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.

(17) REPORT NUMBER /8/3/ /-/ /0/5/4/ / / /0/3/ /L/ /-/ /0/  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
/E/ (18) /E/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /N/ (23) /Y/ (24) /A/ (25) /C/1/7/5/ (26)

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / A retaining ring on the sequencing bar pin was missing. Without the retaining /  
/1/1/ / ring the pin worked out of position. The pin was repositioned correctly. A /  
/1/2/ / Maintenance Request (MR) worked on August 9, 1983 to fix the problem, adjusted /  
/1/3/ / the striker due to a misunderstanding. Another MR was issued on August 22, 1983 /  
/1/4/ / to install a retaining ring on the sequencing bar pin. /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
/1/5/	/E/ (28)	/1/0/0/ (29)	/ NA / (30)	/A/ (31) / Operator Observation /
ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)	
/1/6/	/Z/ (33)	/Z/ (34)	/ NA /	/ NA /
PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION (39)		
/1/7/	/0/0/0/ (37)	/Z/ (38)	/ NA /	
PERSONNEL INJURIES NUMBER	DESCRIPTION (41)			
/1/8/	/0/0/0/ (40)	/ NA /		
LOSS OF OR DAMAGE TO FACILITY (43) TYPE	DESCRIPTION			
/1/9/	/Z/ (42)	/ NA /		
PUBLICITY ISSUED	DESCRIPTION (45)			
/2/0/	/N/ (44)	/ NA /		

NAME OF PREPARER E. Wayne Harrell PHONE (703) 894-5151

NRC USE ONLY

**Vepco**

USNRC REGION II  
ATLANTA, GEORGIA

83 AUG 31 9:23  
VIRGINIA ELECTRIC AND POWER COMPANY  
NORTH ANNA POWER STATION  
P. O. BOX 402  
MINERAL, VIRGINIA 23117

August 24, 1983

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 2900  
Atlanta, Georgia 30303

Serial No. N-83-126  
NO/RCS: 11  
Docket No. 50-338  
License No. NPF-4

Dear Mr. O'Reilly:

Pursuant to North Anna Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following License Event Report applicable to North Anna Unit No. 1.

Report No.


Applicable Technical Specifications

LER 83-054/03L-0

T.S. 6.9.1.9.b

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review.

Very Truly Yours,



E. Wayne Harrell  
Station Manager

Enclosures (3 copies)

cc: Document Control Desk (1 copy)  
016 Phillips Bldg.  
U.S. Nuclear Regulatory Commission  
Washington, D. C. 20555

OFFICIAL COPY

IE 22  
111