

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0.76 ± 16.04%

NARRATIVE REPORT
FOR LER 50-321/1983-082

LICENSEE : GEORGIA POWER COMPANY
FACILITY NAME : EDWIN I. HATCH
DOCKET NUMBER : 50-321

Tech. Specs. section(s) which requires report:

This 30 day LER is required by Tech. Specs. section 6.9.1.9.c, because it showed that the unit was not meeting the requirements of Tech. Specs. sections 3.5.K.1 and 3.5.K.2.

Plant conditions at the time of the event(s):

The plant was in a steady state of operation at 2430 MWT (approximately 100% power).

Detailed description of the event(s):

On 07/29/83, during performance of a control room panel walkdown, it was discovered that the HPCI pump room cooler (1T41-B005B) indicator light was not lit on control room panel 1H11-P654. This indicated that HPCI pump room cooler 1T41-B005B was inoperable. This event is contrary to Tech. Specs. sections 3.5.K.1 and 3.5.K.2 which requires that both coolers be operable in order for HPCI to be considered operable.

Consequences of the event(s):

This event had no effect upon plant operations. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

Cooler 1T41-B005A (100% capacity) was operable during this event.

Justification for continued operation:

HPCI pump room cooler 1T41-B005B was immediately restored to operable status by placing its circuit breaker in the "on" position, thus satisfying the requirements of Tech. Specs. section 3.5.K.1 and 3.5.K.2.

If repetitive, number of previous LER:

This event is non-repetitive.

Narrative Report for LER 50-321/1983-082
Page Two

Impact to other systems and/or Unit:

This event had no impact upon any other Unit 1 system or on Unit 2.

Cause(s) of the event(s):

An investigation revealed that this event was the result of the HPCI pump room cooler's (1T41-B0058) electrical power circuit breaker being in the "off" position. The investigation failed to reveal the reason for the circuit breaker being in the "off" position.

Immediate Corrective Action:

An individual was immediately dispatched to the motor control center to check the position of the HPCI pump room cooler's circuit breaker. The cooler's circuit breaker was found in the "off" position. The circuit breaker was placed in the "on" position, and the fans started. The cooler performed satisfactorily, and was considered operable.

Supplemental Corrective Action:

No supplementary action was taken.

Scheduled (future) corrective action:

No future corrective action is scheduled.

Action to prevent recurrence (if different from corrective actions):

N/A

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444

USNRC REGION II
ATLANTA, GEORGIA

83 SEP 2 09:41



Georgia Power

Edwin I. Hatch Nuclear Plant


August 18, 1983
GM-83-801

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-321

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Attached is Licensee Event Report No. 50-321/1983-082. This report is required by Hatch Unit 1 Technical Specifications Section 6.9.1.9.c.


H. C. Nix
General Manager

3cc
HCN/SBT/djs

xc: R. J. Kelly
G. F. Head
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
S. B. Tipps
R. D. Baker
Control Room
Document Control

OFFICIAL COPY

IE 22
111