



# Entergy Operations

Entergy Operations, Inc.  
Route 3, Box 137G  
Russellville, AR 72801  
Tel 501-964-3100

November 2, 1994

2CAN119402

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Electrical Circuitry Isolation Requirements

Gentlemen:

During the electrical distribution system functional inspection (EDSFI) conducted for Arkansas Nuclear One, Unit 2 (ANO-2), a concern was raised regarding circuitry isolation. The NRC requested Entergy Operations to reassess the existing coordination of the primary and secondary containment penetration overcurrent protective devices to assure that adequate protection was provided for the full range of overcurrent conditions (short-circuits and overloads) for the affected circuits.

In response to the NRC's request, Entergy Operations submitted a letter to the NRC dated September 4, 1992 (OCAN099202). This letter stated, in part, that eleven replacement breakers would be installed in the next practical refueling outage for ANO-2 in an effort to improve the overcurrent protection on identified circuits by providing enhanced breaker coordination in the overload region of the penetration conductor damage curves.

Following the September 4, 1992 submittal, an evaluation was performed which determined that the breaker replacements were not necessary. The purpose of this letter is to ensure that the information on the docket is clear regarding ANO's intention to not install the replacement breakers.

The letter which accurately reflects ANO's commitment to resolve this issue is ANO's letter to the NRC dated April 30, 1993 (OCAN049305). In this letter, ANO committed to revise the Unit 2 penetration study to include consideration of penetration circuit faults in the overload region. The revised study was submitted to the NRC on August 20, 1993 (OCAN089304). The revised study determined that all penetrations were protected in the

070044

9411070299 941102  
PDR ADOCK 05000368  
Q PDR


4001/0

overload fault current region by at least one protective device. This determination negates the need to change any circuit breakers.

The NRC responded to our April 30, 1993, correspondence in a letter dated February 23, 1994 (0CNA029402), which concluded that no further action on our part was necessary at this time. The NRC indicated that they may still have differing opinions with ANO regarding the requirements of ANO's licensing basis and the interpretation of the regulatory guidance. The letter further stated that the NRC was pursuing the matter generically, but that ANO's current position was acceptable.

ANO intends to stay abreast of industry and regulatory developments regarding this matter and will take appropriate actions as necessary. Should you have questions or comments, please contact me.

Very truly yours,



Dwight C. Mims  
Director, Licensing

DCM/dwb

cc: Mr. Leonard J. Callan  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011-8064

NRC Senior Resident Inspector  
Arkansas Nuclear One  
1448 S. R. 333  
Russellville, AR 72801

Mr. George Kalman  
NRR Project Manager Region IV/ANO-1 & 2  
U. S. Nuclear Regulatory Commission  
NRR Mail Stop 13-H-3  
One White Flint North  
11555 Rockville Pike  
Rockville, MD 20852