

**LICENSEE EVENT REPORT**

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	A	P	P	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5				
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

CON'T

REPORT SOURCE L 6 0 5 0 - 0 2 9 3 7 0 6 1 6 8 3 8 0 7 1 4 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On 6/16/83, during a startup from cold shutdown, an overtravel alarm was received during a routine coupling check for control rod 30-51 indicating a possible uncoupled rod. T.S. 3.3.B requires all control rods be coupled (to assure blade movement with the drive.) This type event is analyzed in FSAR Sec.4.7.i. This event caused no threat to the public health and safety. LER 77-27 also reported an uncoupled rod (#46-39).

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE	
R	B	E	X	C	O	N	R	O	D	Z	Z
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
8	3		0	3	6	/	0	3	L	-	0
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER			
X	C	Z	Z	0	0	0	N	N	N	G	0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | No root cause can be determined at this time. Procedure 2.4.2 was immediately

1 1 | used to "recouple" and verify the drive position. Station procedures are con-

1 2 | sidered adequate to assure control rod drive status and the subject drive will

1 3 | be monitored for any future overtravel indications.

1 4  
7 8 9  
FACILITY STATUS  
1 5 C 28 0 0 0 29 N/A 30  
METHOD OF DISCOVERY  
B 31 Routine test 32  
DISCOVERY DESCRIPTION

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) N/A N/A

PERSONNEL EXPOSURES		TYPE		DESCRIPTION (39)
NUMBER				
1	7	0	0	N/A
		37	Z	

PERSONNEL INJURIES		DESCRIPTION (41)	
NUMBER			
1	8	0	0
		40	N/A

8 9 11 12  
LOSS OF OR DAMAGE TO FACILITY  
TYPE DESCRIPTION (43)  
1 9 [Z] (42) N/A  
DE 22  
v/1

PUBLICITY  
 ISSUED DESCRIPTION (45)  
 2 0 N (44)  
 8307220206 830714  
 PDR ADOCK 05000293  
 S PDR  
 NRC USE ONLY

NAME OF PREPARER G.G. Whitney

PHONE: (617) 746-7900

BOSTON EDISON COMPANY  
800 BOYLSTON STREET  
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON  
SENIOR VICE PRESIDENT  
NUCLEAR

July 14, 1983

BECO. Ltr. #83-184

Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406


Docket Number 50-293  
License DPR-35

Dear Sir:

The attached Licensee Event Report 83-036/03L-0, "Control Rod 30-51", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.b.

If there are any questions on this subject, please contact us.

Respectfully submitted,



William D. Harrington

WDH/mg

Enclosure: LER 83-036/03L-0

cc: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Standard BECO. LER Distribution

IER  
1/1