

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

80 L 6 0 5 0 0 0 2 3 7 7 0 6 1 7 8 3 3 0 7 1 4 8 3 9
81 DOCKET NUMBER 68 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

09		SYSTEM CODE C C		CAUSE CODE B		CAUSE SUBCODE C		COMPONENT CODE S U P P O R T				COMP. SUBCODE D		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER 17		EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 5 0		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN E		FUTURE ACTION Z	
23		24		25		26		27		28		29		30	
EFFECT ON PLANT C		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER P 0 2 9		31	
33		34		35		36		37		38		39		40	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27															

1 0 | The cause was believed to be inadequate tightening of the clamp bolts during
1 1 | original installation. The snubber was stroke tested for operability and the
1 2 | clamp and snubber were properly aligned. All other drywell snubbers were visually
1 3 | inspected and no similar problems were noted. Inspections of snubbers will
1 4 | continue per Tech Spec Table 4.6.I.

8 9
FACILITY STATUS (28) 1 5 G 29 0 0 0 N/A 30
7 8 9 10 11 12 13 44
METHOD OF DISCOVERY (31) B 32 Visual Snubber Inspection 45 46 80
DISCOVERY DESCRIPTION (32)
35
ACTIVITY CONTENT (35) 1 6 Z 33 34 N/A 44
7 8 9 10 11 12 13 44
RELEASED OF RELEASE (33) 34
AMOUNT OF ACTIVITY (35)
36
LOCATION OF RELEASE (36) 45 46 80
N/A

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	00	(37) Z (38) N/A (39)

PERSONNEL INJURIES	
NUMBER	DESCRIPTION (41)
0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) N/A
8307220231 830714

7 8 9 10
 PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N (44) N/A
 7 8 9 10 68 69 70
 PDR ADOCK 05000237
 S PDR
 NRC USE ONLY

PHONE: (815) 942-2920 x422



Commonwealth Edison

DEVIATION REPORT

DVR NO. 12 - 2 - 83 - 90
STA UNIT YEAR NO.

PART 1 TITLE OF DEVIATION

Loose Clamp on "A" MSL Snubber #42

OCCURRED

6-17-83

2230

DATE

TIME

SYSTEM AFFECTED 250

PLANT STATUS AT TIME OF EVENT

Main Steam System

MODE Shutdown PWR(MWT) --- LOAD(MWE) ---

TESTING

☒☐

YES

NO

DESCRIPTION OF EVENT

While performing visual exams on Main Steam Line Snubbers as

part of the investigation into previous snubber failures, snubber #42 on "A" MSL was

found loose and had dropped approximately 2 inches from normal position. Clamp was

repositioned to correct position and re-tightened. All drywell snubbers were visually

inspected and no other abnormalities found.

10 CFR50.72 NRC RED PHONE

☐☒

NOTIFICATION MADE

YES

NO

EQUIPMENT FAILURE D28670

☒

YES

☐

NO

WORK REQUEST NO.

RESPONSIBLE SUPERVISOR J. Kotowski

DATE

6/20/83

PART 2 OPERATING ENGINEER'S COMMENTS

None

☐ EVENT OF PUBLIC INTEREST☐ TECH. SPEC. VIOLATION☐ NON REPORTABLE OCCURRENCE☐ 14 DAY REPORTABLE/T.S.☒ 30 DAY REPORTABLE/T.S. 6.6.B.2.b☐ ANNUAL/SPECL REPORT REQ'D☐ 24-HOUR NRC NOTIFICATION REQ'DTELEPH N/A

REGION III

DATE

TIME

TELEGM/TELECOPY N/A

REGION III

DATE

TIME

☐ CECO CORPORATE NOTIFICATION MADE

IF ABOVE NOTIFICATION IS PER 10CFR21

☐ 5-DAY WRITTEN REPORT REQ'D PER 10CFR21

Telecopy

Dennis P. Galle

6-20-83

1152

~~RECEIVED~~

CECO CORPORATE OFFICER

DATE

TIME

PRELIMINARY REPORT
COMPLETED AND REVIEWED

John M. Almer

OPERATING ENGINEER

6-20-83

DATE

INVESTIGATED REPORT & RESOLUTION
ACCEPTED BY STATION REVIEW*[Signature]* 7/14/83*[Signature]* 7/14/83RESOLUTION APPROVED AND
AUTHORIZED FOR DISTRIBUTION*[Signature]*
STATION SUPERINTENDENT7/14/83
DATE



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

July 14, 1983

DJS Ltr #83-696

James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #83-50/03L-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

JUL 18 1983

1E2V
11