

## 3150-0011

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COM. SUBCODE		VALVE SUBCODE								
0	9	S	F	11	A	12	C	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26			
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE						REPORT TYPE		REVISION NO.								
17	8	3	21	22	23	0	9	5	24	25	26	27	28	29	30	31	32	0				
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRO-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER														
H	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	N	24	Z	25	Z	9	9	9	9
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
1	5	E	(28)	1 0 0 (29)	NA
				A (31)	Operator Observation

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 (33) Z (34) NA (35)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7		0	0	0	37	Z	38	NA

PERSONNEL INJURIES  
NUMBER DESCRIPTION (41)

7	8	9	10	11	12
1	8	0	0	0	NA

LOSS OF OR DAMAGE TO FACILITY  
TYPE DESCRIPTION (43)

1 9 2 (42) NA TE22

PUBLICITY  
 ISSUED DESCRIPTION (45)  
 2 0 N (44)  
 7 8 9 10  
 8308010440 830719  
 PDR ADOCK 05000387  
 S PDR  
 NRC USE ONLY

NAME OF PREPARER A.P. Piemontese

PHONE (717) 542-2181



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

July 19, 1983

Dr. Thomas E. Murley  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 83-095/03L-0  
ER 100450 FILE 841-23  
PLA-1751

---

Dear Dr. Murley:

Attached please find a copy of Licensee Event Report No. 83-095/03L-0. This event was determined to be reportable per Technical Specification 6.9.1.9.b, in that during surveillance testing a High Pressure Coolant Injection System (HPCI) isolation signal was received. A meter was incorrectly connected across terminals in the "B" channel of the Turbine Exhaust Diaphragm Pressure Instrumentation while testing was performed on the "D" channel. The condition was immediately corrected.

H.W. Keiser  
Superintendent of Plant-Susquehanna

APP/pjg

cc: G.G. Rhoads  
Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 52  
Shickshinny, PA 18655

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

IE22  
11