

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F I L T P S 3 02 0 0 - 0 0 0 0 0 0 - 0 0 03 4 1 1 1 1 04 05

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CON'T 01 L 02 0 5 0 0 0 2 5 0 07 0 6 2 4 8 3 08 0 7 2 5 8 3 09

REPORT SOURCE 80 DOCKET NUMBER 88 89 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During normal operation, a malfunction of the fire ionization detector 3-10 required

03 the Unit 3 inside containment fire detection Zone 3 to be disabled for longer than 14

04 days. This is reportable pursuant with T.S.3.14.1.b.2 and T.S.6.9.2.b.2. The health

05 and safety of the public were not affected. Similar LERs were reported as 251-80-11

06 and 251-80-13.

07

08

09

SYSTEM CODE 9 A B 11 E 12 X 13 I N S T R U 14 E 15 Z 16

CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP SUBCODE 14 VALVE SUBCODE 15

17 8 3 18 0 1 1 19 0 3 20 L 21 22 0

LER/RO REPORT NUMBER 23 EVENT YEAR 24 SEQUENTIAL REPORT NO. 25 OCCURRENCE CODE 26 REPORT TYPE 27 REVISION NO.

ACTION TAKEN 33 X 34 C 35 Z 36 Z 37 0 0 0 0 40 N 41 N 42 A 43 P 4 3 5 47

ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPD-4 FORM 508 PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The root cause has not been determined. Compensatory measures are: 1) monitoring

11 the containment air temperature as per T.S.3.14.1.b.1 and 2) scheduling of repairs to

12 be performed during the next Unit 3 refueling outage.

13

14

15 E 16 1 0 0 17 N/A 18 C 19 Visual Inspection 20

FACILITY STATUS 21 % POWER 22 OTHER STATUS 23 METHOD OF DISCOVERY 24 DISCOVERY DESCRIPTION

15 E 16 1 0 0 17 N/A 18 C 19 Visual Inspection 20

ACTIVITY CONTENT 21 RELEASED OF RELEASE 22 AMOUNT OF ACTIVITY 23 LOCATION OF RELEASE

15 Z 16 Z 17 N/A 18 N/A 19

PERSONNEL EXPOSURES 20 NUMBER 21 TYPE 22 DESCRIPTION

15 0 0 0 16 Z 17 N/A 18

PERSONNEL INJURIES 20 NUMBER 21 DESCRIPTION

15 0 0 0 16 N/A 17

LOSS OF OR DAMAGE TO FACILITY 20 TYPE 21 DESCRIPTION

15 Z 16 N/A 17

PUBLICITY 20 ISSUED 21 DESCRIPTION

15 N 16 N/A 17

NAME OF PREPARER Jesus Arias, Jr. PHONE (305) 245-2910 Ext. 200

USNRC REGION II
ATLANTA, GEORGIA



83 JUL 28 A9:28

July 25, 1983
PNS-LI-83-516-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-83-11

TURKEY POINT UNIT 3

DATE OF OCCURRENCE: JUNE 24, 1983

TECHNICAL SPECIFICATION 3.14.1.b.2

FIRE DETECTION ZONE 3

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PKG/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

OFFICIAL COPY

7622
1/1