

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT
/0/1/ REPORT
SOURCE /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/6/2/6/8/3/ (8) /0/7/2/1/0/3/ (9)
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On June 26, 1983, while conducting a surveillance test, conditioning module TC-MM/
/0/3/ / 100A-1 which inputs to the Meteorological 33 ft. temperature chart recorder was /
/0/4/ / found to have drifted by 1.15 degrees F. This is greater than tolerances set /
/0/5/ / forth by Safety Guide 23. Since delta temperature and wind speed channels re- /
/0/6/ / mained in tolerance for the evaluation of atmospheric diffusion the health and /
/0/1/ / safety of the public were not affected. This event is reportable pursuant to /
/0/8/ / T.S. 6.9.1.9.b. A similar event was reported in LER 83-025. /

SYSTEM CAUSE CAUSE COMP. VALVE
CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE

/0/9/ /M/C/ (11) /X/ (12) /Z/ (13) /I/N/S/T/R/U/ (14) /Y/ (15) /Z/ (16)
LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION
(17) REPORT NUMBER /8/3/ /-/ /0/3/7/ / / /0/3/ /L/ /-/ /0/
NUMBER

ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPD-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER

/E/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /N/ (23) /Y/ (24) /L/ (25) /T/1/5/5/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The event was caused by instrument drift. The module was subsequently recalibrated. This event has no generic implications.
/1/1/ /
/1/2/ /
/1/3/ /
/1/4/ /

FACILITY STATUS %POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
/1/5/ /E/ (28) /1/0/0/ (29) / NA / /B/ (31) / Surveillance Testing /

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
/1/6/ /Z/ (33) /Z/ (34) / NA / / NA /

PERSONNEL EXPOSURES
NUMBER TYPE DESCRIPTION (39)
/1/7/ /0/0/0/ (37) /Z/ (38) / NA /

PERSONNEL INJURIES
NUMBER DESCRIPTION (41)
/1/8/ /0/0/0/ (40) / NA /

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
/1/9/ /Z/ (42) / NA /

PUBLICITY
ISSUED DESCRIPTION (45)
/2/0/ /N/ (44) / NA /

NRC USE ONLY

NAME OF PREPARER E. Wayne Harrell

PHONE (703) 894-5151

8308040060 830721
PDR ADOCK 05000338
S PDR

JE 22

Vepco

USNRC REGION II
ATLANTA, GEORGIA

VIRGINIA ELECTRIC AND POWER COMPANY
83 JUL 1 10:29
NORTH ANNA POWER STATION
P. O. BOX 402
MINERAL, VIRGINIA 23117

July 21, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

Serial No. N-83-100
NO/FTT: 11
Docket No. 50-338
License No. NPF-4

Dear Mr. O'Reilly:

Pursuant to North Anna Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following License Event Report applicable to North Anna Unit No. 1.

Report No.


Applicable Technical Specifications

LER 83-037/03L-0

T.S. 6.9.1.9.a

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review.

Very Truly Yours,


E. Wayne Harrell
for Station Manager

Enclosures (3 copies)

cc: Document Control Desk (1 copy)
016 Phillips Bldg.
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

1022
||