



Entergy  
Operations

Ref: 10CFR50.73(a)(2)(iv)

Entergy Operations, Inc.

PO Box 8

Spring LA 70465

Telex 159-0045

W3B5-91-0188

A4.05

QA

June 25, 1991

U.S. Nuclear Regulatory Commission  
ATTENTION: Document Control Desk  
Washington, D.C. 20555

Subject: Waterford 3 SES  
Docket No. 50-382  
License No. NPF-38  
Submittal of Licensee Event Report

Gentlemen:

Attached is Licensee Event Report Number LER-90-004-01 for Waterford Steam Electric Station Unit 3. This Licensee Event Report supplement is submitted to provide additional causal information resulting from diagnostic testing of the failed component. This Licensee Event Report is submitted pursuant to 10CFR50.73 (a)(2)(iv).

Very truly yours,

D.F. Packer  
General Manager - Plant Operations

DFP/LDC/rk  
Attachment

cc: Messrs. R.D. Martin  
G.L. Florreich  
J.T. Wheelock - INPO Records Center  
E.L. Blake  
D.L. Wigginton  
N.S. Reynolds  
NRC Resident Inspectors Office

9106270331 910625  
FDR ADOCK 05000382  
S FDR

IF22  
11

## LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-80), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545, AND TO THE PAPERWORK REDUCTION PROJECT (2160-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1):

Waterford Steam Electric Station Unit 3

DOCKET NUMBER (2):

0 5 0 0 0 3 8 2 1 OF 0 4

PAGE (3):

TITLE (4):

Inadvertent Emergency Feedwater System Actuation Due to Test Circuit Malfunction

EVENT DATE (5):			LER NUMBER (6):			REPORT DATE (7):			OTHER FACILITIES INVOLVED (8):		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	RELATION TO PREVIOUS	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	4	0	8	9	0	9	0	0	0	0	0
0	4	0	8	9	0	9	0	0	0	0	0
OPERATING MODE (9):			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50.71 (Check one or more of the following) (13):								
POWER LEVEL (10):			20.402(b) <input checked="" type="checkbox"/> 20.405(c) <input checked="" type="checkbox"/> 50.73(a)(2)(iv) <input type="checkbox"/> 73.71(b) <input type="checkbox"/>								
11010			20.405(a)(1)(i) <input type="checkbox"/> 50.36(a)(1) <input type="checkbox"/> 50.73(a)(2)(v) <input type="checkbox"/> 73.71(c) <input type="checkbox"/>								
			20.405(a)(1)(ii) <input type="checkbox"/> 50.36(a)(2) <input type="checkbox"/> 50.73(a)(2)(vi) <input type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 308a) <input type="checkbox"/>								
			20.405(a)(1)(iii) <input type="checkbox"/> 50.73(a)(2)(ii) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/>								
			20.405(a)(1)(iv) <input type="checkbox"/> 50.73(a)(2)(iv) <input type="checkbox"/> 50.73(a)(2)(vii) <input type="checkbox"/>								
			20.405(a)(1)(v) <input type="checkbox"/> 50.73(a)(2)(vi) <input type="checkbox"/> 50.73(a)(2)(viii) <input type="checkbox"/>								
			20.405(a)(1)(vi) <input type="checkbox"/> 50.73(a)(2)(viii) <input type="checkbox"/>								

LICENSEE CONTACT FOR THIS LER (12):

NAME

W.R. Brian, Plant Engineering Superintendent

TELEPHONE NUMBER

AREA CODE

5 1 014 4 614 -1311 217

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13):

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
B	J	C	C	N	T	R	C	7	7

SUPPLEMENTAL REPORT EXPECTED (14):

EXPECTED SUBMISSION DATE (15):

MONTH DAY YEAR

YES (1) OR COMPLETE EXPECTED SUBMISSION DATE:

X NO

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

At 0444 hours on April 8, 1990, Waterford Steam Electric Station Unit 3 was operating at 100% power when a partial actuation of the Emergency Feedwater (EFW) system occurred during a scheduled functional test of the Plant Protection System (PPS). This event is reportable as an unplanned Engineered Safety Feature (ESF) actuation. The actuation was not of sufficient duration to allow EFW flow to the Steam Generators (SG).

The root cause of this event is test circuit malfunction. The matrix test module relay hold pushbutton assembly was replaced and the PPS functional test was completed satisfactorily. Further diagnostic testing and evaluation of the relay hold pushbutton isolated the cause of the circuit malfunction to be the incorrect assembly of the early closing contact block. Because the circuit malfunction was associated only with the test circuitry and the EFW System was capable of responding in the safe direction, this event did not threaten the health and safety of the general public or plant personnel.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530) U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104) OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (3)

PAGE (3)

Waterford Steam  
Electric Station Unit 3YEAR SEQUENTIAL  
NUMBER REVISION  
NUMBER

0 5 0 0 0 3 8 2 9 0 - 0 0 4 - 0 1 0 2 OF 0 4

TEXT (If more space is required, use additional NRC Form 360A (1/17))

At 0444 hours on April 8, 1990, Waterford Steam Electric Station Unit 3 was operating at 100% power when a partial actuation of the Emergency Feedwater (EFW) (EIIIS Identifier - BA) occurred during a scheduled functional test of the Plant Protection System (PPS) (EIIIS Identifier - JC). This event is reportable as an unplanned engineered safety feature (ESF) actuation.

While performing step 85 of operating procedure (OP) 903-107, "Plant Protection System Channel Functional Test," which involves pressing and holding the PPS matrix relay hold pushbutton and verifying system response, all three EFW pumps (EIIIS Identifier 7A-P) and Steam Generator (SG) (EIIIS Identifier-SG) blowdown System Isolation Valves (EIIIS Identifier WI-ISV) actuated. The EFW to SG isolation valves did not open due to the short duration of the actuation signal. The functional test was terminated and EFW system components were returned to their normal configuration. The inadvertent actuation could not be reproduced and the functional test was later reperformed with satisfactory results.

The matrix relay hold pushbutton performs three functions. 1) It interrupts test power to the matrix test modules (EIIIS Identifier - IMOD) not being tested. 2) It provides test power to the matrix bistable relay aiding coils (EIIIS Identifier - RLY/GL) through the use of early closure contacts (EIIIS Identifier - CNTR) on the pushbutton. 3) It provides test power to the matrix bistable relay opposing coils.

During the circuit test sequence, the relay hold pushbutton is depressed and through use of the early closure contacts, applies test power to the aiding coils of the matrix trip path relays before the bistable relays are deenergized. If the bistable relays deenergize the matrix trip path relay primary coils before the matrix relay aiding coils energize, an Emergency Feedwater Actuation Signal (EFAS) (EIIIS Identifier BA-JE) will result.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1):

DOCFET NUMBER (2):

LER NUMBER (6):

PAGE (3):

Waterford Steam  
Electric Station Unit 3

0 5 0 0 0 3 8 2 9 0 - 0 0 4 - 0 1 0 3 OF 0 4

TEXT (If more space is required, use additional NRC Form 365A's) (17)

During troubleshooting performed on May 3, 1990, the relay hold pushbutton and contact blocks for the A-C matrix test module were examined and revealed a higher than normal resistance across the early opening contacts. The resistance measured in the range of 1.9 to 28 ohms, compared to a normal resistance of 0.2 ohms. Bench testing of the relay hold pushbutton indicated that the contact resistance varied with the degree of pressure applied to the pushbutton and that the contact resistance did not delay energizing the matrix bistable relay aiding coil.

Diagnostic testing of the removed pushbutton was completed. Neither carbon or corrosion buildup on the contacts was found. Evaluation by a vendor (Combustion Engineering, Inc.) determined that the root cause of the test circuit malfunction was the incorrect assembly of the Cutler-Hammer early closing contact block (model number 2 N.O. 10250T57), which resulted in poor electrical contact.

The relay hold pushbutton and contacts were replaced and the A-C matrix was tested satisfactorily on May 3, 1990. The five other relay hold pushbutton switches were replaced prior to April 19, 1991. All five contact blocks were x-rayed and found to be assembled correctly. One of the early closing contact blocks was found to be incorrectly labeled. The early closing symbol was stamped on the wrong side of the contact block.

Corrective action to prevent recurrence of this event is to verify that the function of the contact block is stamped correctly on the block and to x-ray all Cutler-Hammer contact blocks before installation in safety equipment in order to verify proper assembly. These actions will continue until the quality control of the manufacturer is upgraded. A part 10CFR21 evaluation is being performed. All plant safety related equipment that use the Cutler-Hammer contact block (model number 2 N.O. 10250T57) will be identified and verified for proper assembly.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-830), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Waterford Steam Electric Station Unit 3	DOCKET NUMBER (2)  0 5 0 0 2 3 8 2	LER NUMBER (6)			PAGE (3)		
		YEAR  9 0	SEQUENTIAL NUMBER  — 0 0 4	REVISION NUMBER  — 0 1			

TEXT (If more space is required, use additional NRC Form 306A's) (17)

The circuit malfunction was limited to the PPS test circuitry and would not have impaired the ability of the EFW system or any other related safety systems to respond to an actual demand on the PPS if required. The functional test in progress at the time of the EFAS was later completed satisfactorily. For these reasons, the health and safety of the general public was not jeopardized during this event.

Similar Events

None

Plant Contact

W.R. Brian, Plant Engineering Superintendent, 504/464-3127.