

# LICENSEE EVENT REPORT

Updated Report  
Previous Report Date: 4/27/83

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: 01 I L D R S 2 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5  
 LICENSE NUMBER: 25 26 LICENSE TYPE: 30 57 CAT: 58

CON'T  
 REPORT SOURCE: 01 L 6 0 5 0 0 0 2 3 7 7 0 4 0 3 8 3 3 0 7 1 8 8 3 9  
 DOCKET NUMBER: 60 61 EVENT DATE: 68 69 REPORT DATE: 74 75

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During refuel outage operator found no position indication for core spray  
 03 injection valve MO 1402-25B. Operator attempted to open the valve, but would not  
 04 open. There was no effect to public health and safety. The event is of minimal  
 05 safety significance since other safety systems were operable and the unit was shut  
 06 down. Previous occurrence reported by R.O. 83-20 on Docket 50-237.  
 07  
 08  
 09

SYSTEM CODE: 09 S F 11 CAUSE CODE: D 12 CAUSE SUBCODE: Z 13 COMPONENT CODE: C K T B R K 14  
 COMP. SUBCODE: A 15 VALVE SUBCODE: Z 16  
 LER/RO REPORT NUMBER: 17 8 3  
 EVENT YEAR: 21 22 8 3  
 SHUTDOWN METHOD: 23 Z 21  
 HOURS: 22 0 0 0 0  
 ATTACHMENT SUBMITTED: 23 N 23  
 NPD-4 FORM SUB: 24 Y 24  
 PRIME COMP. SUPPLIER: 25 N 25  
 COMPONENT MANUFACTURER: 26 G 0 8 0  
 SEQUENTIAL REPORT NO.: 24 0 2 2  
 OCCURRENCE CODE: 27 0 3  
 REPORT TYPE: 30 X  
 REVISION NO.: 32 1

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Event due to equipment failure and inadequate procedure. Originally, the breaker  
 11 tripped below nameplate setting. Breaker was replaced. Subsequently found wrong  
 12 breaker setting of 2 because of use of incorrect breaker data sheet not controlled  
 13 by station procedure. Breaker was set at 5 and corrected data sheet is being added  
 14 to a station procedure.

FACILITY STATUS: 15 H 28 % POWER: 29 0 0 0 0 OTHER STATUS: 30 N/A METHOD OF DISCOVERY: 31 A 31  
 DISCOVERY DESCRIPTION: 32 Operator Observation  
 ACTIVITY CONTENT: 33 Z 33 RELEASED OF RELEASE: 34 Z 34 AMOUNT OF ACTIVITY: 35 N/A LOCATION OF RELEASE: 36 N/A

PERSONNEL EXPOSURES: 37 0 0 0 37 38 Z 38 N/A  
 PERSONNEL INJURIES: 39 0 0 0 40 N/A

LOSS OF OR DAMAGE TO FACILITY: 41 0 0 0 42 N/A  
 TYPE: 43 Z 42 DESCRIPTION: 44 N/A

PUBLICITY: 45 2 0 46 N/A  
 ISSUED DESCRIPTION: 47 N/A

NAME OF PREPARER

L. Coyle

PHONE: (815) 942-2920 x526

8308040269 830718  
 PDR ADOCK 05000237  
 S PDR

NRC USE ONLY

# SUPPLEMENT TO DVR

DVR NO.	STA	UNIT.	YEAR	NO.
D - 12	-	2	-	83 - 51

<b>PART 1</b>	<b>TITLE OF EVENT</b>	<b>OCCURRED</b>	
	MO 1402-25B Failure to Open	4/3/83	0830
	<b>REASON FOR SUPPLEMENTAL REPORT</b>	<b>DATE</b>	<b>TIME</b>
	Clarify cause description and change in action taken and future action.		
<b>PART 2</b>			
<b>ACCEPTANCE BY STATION REVIEW</b>	<i>J. Brunner</i>	<i>John M. Allen</i>	
<b>DATE</b>	7/18/83	7/18/83	
<b>SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION</b>	<i>R.M. Pagan Jr</i>		7/20/83
	<b>STATION SUPERINTENDENT</b>		<b>DATE</b>



**Commonwealth Edison**

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

July 18, 1983

DJS Ltr #83-700

James G. Keppler, Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #83-22/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation. Updated report is being submitted to clarify cause description and change action taken and future action.

D.J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Management Branch  
File/NRC

JUL 25 1983

11 IE22