

**LICENSEE EVENT REPORT**

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | | L | L | S | C | | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 0 | 0 | 0 | 4 | | 5  
7 8 9 14 15 25 26 30 37 CAT 38  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CONT

REPORT SOURCE: 01 L 5 0 5 0 0 0 3 7 3 7 0 6 2 4 8 3 2 0 7 2 1 8 3 9  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On June 24, 1983 at 1200 hours with Unit 1 at approximately 70% power, a pinhole

03 | leak in an original weld on line 0WX43AA was found by a station construction engineer

04 | Since the small amount of water leaking from line 0WX43AA drained directly to the

05 | spent resin tank, via the floor drains, the health and safety of the public was not

06 | affected

07 |

7	8	9	SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE			COMP. SUBCODE	VALVE SUBCODE			
0	9		M	D	A	F	P	I	P	E	X	X	A	Z
7	8		9	10	11	12	13					14	15	16
LER/RO REPORT NUMBER			EVENT YEAR			SEQUENTIAL REPORT NO.			OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
17			8	3	—	0	7	0	/	0	3	L	—	0
			21	22	23	24	25	26	27	28	29	30	31	32
ACTION TAKEN		FUTURE ACTION	EFFECT ON PLANT		SHUTDOWN METHOD	HOURS			ATTACHMENT SUBMITTED	NFRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURE
X	Z		Z		Z	0	0	0	0	X	N	Z		Z 9 9
33	34		35		36	37	38	39	40	41	42	43		44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)	
1 0	The cause of this incident was a faulty weld on a 90° elbow joint on line 0WX43AA.
1 1	This is considered an isolated incident. A section of line 0WX43AA is scheduled to
1 2	be repaired under WR #25654 by the station construction department. AIR #1-83-6703
1 3	was initiated to track the completion of the work request.

1	4													
7	8	9												
FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	B	23	0	6	8	29	NA	A	31	Observation			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	
ACTIVITY CONTENT RELEASED			AMOUNT OF ACTIVITY			LOCATION OF RELEASE								
1	6	Z	33	Z	34	NA			NA					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION (39)				
1	7	0	0	0	(37)	Z	(38)	NA	

7	8	9	11	12	13
PERSONNEL INJURIES					
NUMBER			DESCRIPTION		

7	8	9	11	12	NA	8308040312 830721
LOSS OF OR DAMAGE TO FACILITY (43)					PDR	ADOCK 05000373
TYPE DESCRIPTION					S	PDR

1 9 7 42 NA 5 FEB 10

ISSUED (20) N (44) DESCRIPTION NA

NAME OF PREPARER J. J. Arand

PHONE: 357-6761

I. LER NUMBER: 83-070/03L-0

II. LASALLE COUNTY STATION: Unit 1

III. DOCKET NUMBER: 050-373

IV. EVENT DESCRIPTION:

On June 24, 1983 at 1200 hours with Unit 1 at approximately 70% power, a pinhole leak, in an original weld, on line 0WX43AA was found by a station construction engineer.

V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

Since the small amount of water leaking from line 0WX43AA, drained directly to the spent resin tank via the floor drains, the health and safety of the public was not affected.

VI. CAUSE:

The cause of this incident was a faulty weld on a 90° elbow joint on line 0WX43AA. This is considered an isolated incident.

VII. CORRECTIVE ACTION:

A section of line 0WX43AA is scheduled to be repaired under WR #25654 by the station construction department. AIR #1-83-67035 has been initiated to track the satisfactory completion of the work request.

Prepared by John Arand



**Commonwealth Edison**  
LaSalle County Nuclear Station  
Rural Route #1, Box 220  
Marseilles, Illinois 61341  
Telephone 815/357-6761

July 21, 1983

James G. Keppler  
Regional Administrator  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Sir:

Reportable Occurrence Report #83-070/03L-0 Docket #050-373 is being submitted to your office in accordance with LaSalle County Nuclear Power Station Technical Specification 6.6.B.2.(d). Abnormal degradation of systems other than those specified in Item B.1.c above designed to contain radioactive material resulting from the fission process.

*CE Sargent*

*for* G. J. Diederich  
Superintendent  
LaSalle County Station

GJD/CW/sjc

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U. S. NRC Document Management Branch  
Inpo-Records Center  
File/NRC

JUL 25 1983

11 IE22