

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80CONT

0	1	L	6	0	5	0	0	0	3	1	5	7	0	8	1	1	8	3	8	0	9	0	9	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	A BREAKER PANEL WAS TAKEN OUT OF SERVICE FOR ROUTINE BREAKER CLEANING. THE POWER																																																																													
0	3	TO THE PUMP FOR ERS-1400, TRAIN B LOWER CONTAINMENT AIRBORNE MONITOR, WAS REMOVED																																																																													
0	4	AT THIS TIME. THIS IS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFICATION																																																																													
0	5	3.3.3.1. THE HEALTH AND SAFETY OF THE PUBLIC WERE NOT AFFECTED. THIS IS THE FIRST																																																																													
0	6	REPORTABLE EVENT OF THIS NATURE.																																																																													

0	7																																																																														
0	8																																																																														

0	9	M	C	11	X	12	Z	13	I	N	S	T	R	U	14	P	15	Z	16	17	8	3	18	0	8	4	19	0	3	20	L	21	0	22	0	0	0	0	23	N	24	N	25	L	26	E	0	7	0	27
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	----	---	---	----	---	---	---	----	---	---	----	---	----	---	----	---	---	---	---	----	---	----	---	----	---	----	---	---	---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	THE ELECTRICAL DISTRIBUTION DRAWINGS DID NOT ADEQUATELY SHOW THE CORRELATION																																																																													
1	1	BETWEEN THE BREAKER PANEL DISTRIBUTION AND THE TRANSFORMER DISTRIBUTION WHICH																																																																													
1	2	FED THE RMS PUMP BREAKER. THE DRAWING HAS BEEN CHANGED TO SHOW THE CORRELATION.																																																																													
1	3																																																																														
1	4																																																																														

1	5	H	28	0	0	0	29	NA	30	A	31	OPERATOR OBSERVATION																																																																	
---	---	---	----	---	---	---	----	----	----	---	----	----------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

1	6	Z	33	Z	34	NA	35	NA	36
---	---	---	----	---	----	----	----	----	----

1	7	0	0	0	37	Z	38	NA	39
---	---	---	---	---	----	---	----	----	----

1	8	0	0	0	40	NA	41
---	---	---	---	---	----	----	----

1	9	Z	42	NA	43
---	---	---	----	----	----

2	0	N	44	NA	45
---	---	---	----	----	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER D. F. KRAUSE

PHONE (616) 465-5901

8309160141 830909
PDR ADOCK 05000315
S PDR

IF 22



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

September 9, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137


Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,
the following reports are submitted:

RO 83-084/03L-0

Sincerely,


W.G. Smith, Jr.
Plant Manager

/cm

cc: J.E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

SEP 12 1983

IEJ2 1/1