



**Commonwealth Edison**

One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

September 8, 1983

Mr. James G. Keppler, Regional Administrator  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Subject: Byron Generating Station Units 1 and 2  
Braidwood Generating Station Units 1 and 2  
Barton Instrument Accuracy  
NRC Docket Nos. 50-454, 50-455, 50-456,  
and 50-457

---

- References (a): January 28, 1983, letter from T. R. Tramm  
to J. G. Keppler.
- (b): March 28, 1983 letter from T. R. Tramm  
to J. G. Keppler.
- (c): June 1, 1983, letter from T. R. Tramm  
to J. G. Keppler.

Dear Mr. Keppler:

References (a), (b), and (c) provided interim reports on a deficiency reportable pursuant to 10 CFR 50.55(e) regarding the accuracy of Barton electronic instrument transmitters being installed at Byron and Braidwood stations. This letter provides a fourth interim report. For NRC tracking purposes this deficiency is numbered 82-11 for Byron and 82-12 for Braidwood.

As described in the previous interim reports on this deficiency, a design change involving the addition of an insulating washer into the transmitter eliminates the majority of the instrument inaccuracy at accident environment temperatures (325°F). However, an accuracy problem still exists when the transmitter is exposed to abnormal environment temperatures (130°F).

Barton has discovered that this remaining accuracy problem was caused by an incorrect manufacturing methodology used during the temperature compensation process. The corrective action is a revised temperature compensation procedure. The effect on transmitters compensated with the incorrect methodology is a possible increase in the temperature coefficient at 130°F and 325°F.

8309230355 830908  
PDR ADDCK 05000454  
S PDR

SEP 13 1983


110  
IE27

September 8, 1983

A final report on this deficiency is expected to be available in 60 days. This report will include a list of transmitters that require the addition of an insulating washer and a list of transmitters that are affected by the improper temperature compensation. Corrective actions being considered to eliminate the temperature compensation problem are transmitter recalibration, instrument setpoint adjustment, or evaluation of the transmitter inaccuracy for its specific application. The final report will also include the corrective action for each transmitter affected by the temperature compensation problem.

Please address questions regarding this matter to this office.

Very truly yours,



T. R. Tramm  
Nuclear Licensing Administrator

lm

cc: Director of Inspection and Enforcement

7270N