

NAME OF PREPARER R. L. Wenderlich/R. W. L'Heureux PHONE: 301-269-4907/4503

IE22

LER NO. 80-51/1X, Revision 1
DOCKET NO. 50-317
LICENSE NO. DPR 53
EVENT DATE 09-11-80
REPORT DATE 08-19-83
ATTACHMENT

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (CONT'D)

During normal operation of Units 1 and 2 while performing post-maintenance testing of #11 Control Room air conditioning unit, experienced failure of both #11 and #12 Control Room air conditioning units, a violation of T.S. 3.7.6.1. At 1930, #12 Control Room air conditioning unit was secured in order to perform a post-maintenance operational check of #11 Control Room air conditioning unit. When #11 failed to start, an attempt was made to restart #12. However, #12 also failed to start. After corrective maintenance, #12 was restarted at 2005. #11 was later repaired and was returned to service at 1315 on 9/12/80. The Control Room air temperature did not exceed the design limit of 120°F and both filter trains remained operable during the event. Therefore, this event had no affect upon the public health and safety.

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

August 19, 1983

Dr. Thomas E. Murley
Regional Administrator
U. S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406

Docket No. 50-317
License No. DPR 53

Dear Dr. Murley:

Attached is LER 80-51/1X, Revision 1, as required per Technical Specification 6.9.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,

L B Russell

L. B. Russell
Plant Superintendent

LBR:RWL:bsb

cc: Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

IE22
11