

**LICENSEE EVENT REPORT**

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

CON'T

REPORT SOURCE: 0 1 7 8 L 6 0 5 0 - 0 3 2 5 7 0 8 2 4 8 3 8 0 9 1 5 8 3 9  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During Unit No. 1 shutdown and subsequent startup and power operation on August 24, 25,  
0 3 | and 29, 1983, the following control rods had no indications at the identified  
0 4 | positions: rod 26-19 (00, 07, 10, 17, 20, 27, 30, 37, 40, 47), rod 18-51 (07, 17, 27  
0 5 | 37, 47), rod 50-19 (30, 31, 34, 35, 38), rod 22-27 ("full-in"), rod 46-27 (10-19, 22,  
0 6 | 23, 26, 27, 29), rod 26-15 (20, 21, 24, 25, 28), and rod 10-35 (02, 03, 06, 07, 09).  
0 7 | In each case, the public health and safety was not affected.

08 Technical Specifications 3.1.3.7, 6.9.1.9b 80

SYSTEM CODE I B 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE X X X X X X 14				COMP. SUBCODE Z 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 17		EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 0 3 2 24 26		OCCURRENCE CODE / 27		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN X 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. Y 24	
PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER G 0 8 0 0 26 33 34 35 36 37 40 41 42 43 44 47											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The initial investigation of these indication problems has determined they most likely

1 1 | involve the respective position indication probe connectors of the subject control

1 2 | rods. These indication problems will be repaired during a future unit outage which

1 3 | permits sufficient time for further investigation and appropriate repairs.

FACILITY STATUS			% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	D	28	0	0	0	29	NA	A	31	Operational Event
7	8	9	10	11	12	13	14	15	16	17	18

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) NA 44

7 8 9 10 11

LOCATION OF RELEASE (36)

NA 45 80

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	000	(37) Z (38) NA

8309230451 830915

PERSONNEL INJURIES		PDR ADOCK 05000325	
NUMBER	DESCRIPTION	S	PDR
1 8 0 0 0	(40) NA		

8		9		11		12	
1		2		3		4	
TYPE		DESCRIPTION					
1	9	Z	(42)	NA			

TE 20 11

8 9 10 80

PUBLICITY

ISSUED DESCRIPTION (45)

2 0 N (44) NA

NRC USE ONLY

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521

NRC USE ONLY



83 SEP 20 AM 11:24  
Carolina Power & Light Company

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429

September 15, 1983

FILE: B09-13510C  
SERIAL: BSEP/83-3082

Mr. James P. O'Reilly, Administrator  
U. S. Nuclear Regulatory Commission  
Region II, Suite 3100  
101 Marietta Street N.W.  
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1  
DOCKET NO. 50-325  
LICENSE NO. DPR-71  
LICENSEE EVENT REPORT 1-83-32

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical Specifications for Brunswick Steam Electric Plant, Unit No. 1, the enclosed Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July 1977.

Very truly yours,

C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

RMP/pms/LETPS1

Enclosure

cc: Mr. R. C. DeYoung  
NRC Document Control Desk

OFFICIAL COPY  
LE 22

